

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

MCQUEEN RENTALS PTE LTD
c/o 46 Lenton Plain
Singapore 786548

Not Authorized
11 Sep 8 3700h
Assembly After Paint
6 days

Date: 13/8/2018

QUANTITY	PARTICULARS	AMOUNT (\$)
	RE: MAZDA 3 / SLF312B	
1 pc	rear bumper retainer	<i>Di</i> 106.80 ✓
1 pc	rear bumper reinforcement	<i>R</i> 583.20 X
1 pc	rear bumper <i>1129</i>	<i>Buck</i> 1,178.50 ✓
1 pc	rear bumper dust cover	<i>Sm</i> 129.70 X
1 pc	rear fender	<i>As</i> 1,129.70 ✓
1 pc	rear fender dust cover	<i>Sm</i> 138.60 X
1 pc	alloy rim	<i>Red</i> 1,156.30 <i>4 color</i>
1 pc	rear shock absorber	<i>Sm</i> 228.90 X
1 pc	rear lower arm	<i>Sm</i> 257.30 X
1 pc	rear knuckle arm <i>455.30</i>	<i>Sp</i> 486.10 ✓
1 pc	rear wheel bearing hub assy <i>414.40</i>	<i>As</i> 518.30 ✓
1 pc	rear windscreen moulding	<i>As</i> 156.80 ✓
1 pc	rear windscreen seal	<i>As</i> 90.30 ✓
1 pc	control arm	<i>Sm</i> 206.80 X
1 pc	trailing arm	<i>Sm</i> 283.50 X
	Sub-total	6,650.80
	Less 15% <i>20%</i>	997.62
	Sub-total	5,653.18
1 tube	windscreen glass sealant s.nett	<i>As</i> 120.00 <i>40m</i>
	To remove and replace all the parts mentioned above, panel beat and realign the necessary affected areas.	<i>600h</i> 700.00
	sub-total	6,473.18