

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP :37151

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0423/2020/NS
Date : 10-Jun-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Eileen Koh Poh Yip
Address : 135 Chempaka Kuning Link
Singapore 486335
Telephone : HP +65 81829314
Type of Claim : Own Damage Claims
Policy No. : 1900242658
Vehicle No : **SLD 6702 E**
Model Code : Audi A3 Sportsback 1.4 TF
Model / Year : Jun-16
Engine No : CZC C533606
Chassis No : WAUZZZ8V0GA126636
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Jun-20
Place of Accident : SLE Woodlands Ave 12 Exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLD 6702 E

<u>S/N</u>	<u>Nature of Jobs</u>		<u>Estimated Charges</u>	<u>Surveyor's Recommendations</u>
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	✓
2	To remove and renew front bumper, bonnet and both headlights. Re-organise rear crash management components. Reinstall all parts removed.	\$	2,800.00 1000	
3	To respray front bumper, bonnet and hinges. X	\$	2,200.00 1100	
4	To carry out diagnostic check.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 5,552.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 6702 E

S/N	Parts Description	Damage Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER <i>reband</i>	\$	1,756.00	✓
2	FRONT BUMPER FIXING PARTS <i>all n</i>	\$	176.00	+
3	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	147.00	+
4	FRONT BUMPER PULL STRAP - LOWER <i>new</i>	4 \$	194.00	+
5	FRONT BUMPER GUIDE SECTION - LH / RH <i>all n</i>	2 \$	120.00	+
6	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>new</i>	2 \$	206.00	+
7	RADIATOR GRILLE CLOSING ELEMENT <i>constant</i>	\$	650.00	✓
8	RADIATOR GRILLE COVER ?	\$	92.00	?
9	FRONT BUMPER SIDE REINFORCEMENT BEAM ?	\$	681.00	?
10	FRONT BUMPER FOAM FILLER PIECE ?	\$	78.00	?
11	FRONT BUMPER FOAM FILLER PIECE COVER ?	\$	53.00	?
12	CAUTION SIGN STICKER ?	NEC \$	13.00	✓
13	AIRCON STICKER <i>1 n</i>	NEC \$	7.00	✓
14	SIGNAL HORN - LH LOW TONE ?	\$	188.00	+
15	SIGNAL HORN - RH HIGH TONE <i>1 n</i>	\$	188.00	+
16	BONNET <i>Dented</i>	\$	2,581.00	✓
17	BONNET ATTACHMENT PARTS ?	\$	155.00	?
18	BONNET LID HINGE - LH / RH <i>new</i>	2 \$	116.00	+
19	BONNET GAS FILLED STRUT <i>all n</i>	\$	112.00	+
20	BONNET EDGE PROTECTION - FRONT <i>all n</i>	\$	26.00	✓
SUB TOTAL SPARE PARTS CHARGES		:	\$ 7,539.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 6702 E

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	BONNET CATCH HOOK	\$ 84.00	✓
22	BONNET STRIKER - LH / RH	2 \$ 208.00	✓
23	BONNET CATCH HOOK	\$ 60.00	✓
24	BONNET LID LOCK	2 \$ 403.00	✓
25	BONNET BOWDEN CABLE - CENTRE	\$ 54.00	✓
26	HEADLIGHT - LH / RH	2 \$ 3,748.00	?
27	LIFT CYLINDER - LH / RH	2 \$ 362.00	✓
28	LIFT CYLINDER HOSE	\$ 172.00	✓
29	RADIATOR AIR GUIDE - LH / RH	2 \$ 46.00	✓
30	RADIATOR AIR GUIDE - UPPER CENTRE	\$ 12.00	✓
31	FRONT NO PLATE	S/N \$ 60.00	✓
32	SUNDRIES	\$ 400.00	?
TOTAL SPARE PARTS CHARGES		: \$ 13,148.00	
TOTAL LABOUR CHARGES		: \$ 5,552.00	
GRAND TOTAL		: \$ 18,700.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Li
Surveyed Date : 12/06/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 04 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant