

## COMFORTDELGRO ENGINEERING PTE LTD

45 Pandan Road S (609286)

Tel: 68676919 Fax: 62626950

Appendix A

**Spare Parts**

Vehicle No. : **GBC2311A**  
 Make & Model : FIAT DOBLO CARGO 1.3MJ  
 Chassis No. : ZFA26300009110280

Submit By : **Wong Chee Wei**  
 Year Manufacture : 2011  
 Engine No. : 199A30004174966

**OD****S/Order**

S/No	Part Description	Qty	Cost Price		Nett Price	List Price	S- Nett Price
			original	make up 10%			
1	RHS TAIL GATE <i>bt</i>	1	\$1,074.94	\$1,182.43			
2	RHS TAIL GATE TOP LOCK <i>X SVC</i>	1	\$108.93	\$119.82	X		
4	RHS TAIL GATE LOWER LOCK <i>X SVC</i>	1	\$81.88	\$90.06	X		
5	RHS TAIL GATE SIDE WEATHERSTRIP <i>new</i>	1	\$133.32	\$146.65			
7	RHS TAIL GATE UPPER HINGE <i>X SVC</i>	1	\$108.93	\$119.82	X		
8	RHS TAIL GATE LOWER HINGE <i>X SVC</i>	1	\$118.93	\$130.82	X		
9	LHS TAIL GATE <i>repair bt</i>	1	\$1,083.34	\$1,191.67			
10	LHS TAIL GATE CENTER LOCK <i>X SVC</i>	1	\$137.52	\$151.27	X		
11	BODY SIDE WEATHERSTRIP <i>X SVC</i>	1	\$203.78	\$224.15	X		
12	STICKER - COMPANY DECAL - BACK, RHS&LHS FENDER (not covered)			nec	6.00		
13	RHS TAIL GATE GLASS <i>bro</i>	1	\$176.92	\$194.61			X \$1,200.00
14	SEALANT	1					\$40.00
15	BODY SEALANT	1					\$60.00
16		1					
17		1					
18		1					
19		1					
20		1					
21		1					
22		1					
23		1					
24		1					
25		1					
26		1					
27		1					
28		1					
29		1					
30		1					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

45 Pandan Road S (609386)

## Appendix B

Vehicle No. : **GBC2311A**

Submit By : : Wong Chee Wei

Make & Model : FIAT

Year of Manufacture : 2011

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*