



CHENG HOE MOTOR PTE LTD

Blk 1019, Yishun Industrial Park A, #01-374/382, Singapore 768761
Tel : 67556142 Fax : 67557719
Email: chmotor@singnet.com.sg

China Taiping Insurance (Singapore) Pte. Ltd. (HQ)
TRUCTION PTE LTD

NTUC Income Insurance Co-operative Ltd

OF CLAIM

THIRD PARTY

SLN2882S

UNKNCWN

HOO SENG HIN DANIEL

Ref. No:

TP/CHINA (GBB5256L)

Date of Loss:

15/06/2020

Driveable?

HONDA VEZEL, 1.5 (A)

BLUE

L15B4405191

0 KM

Vehicle Reg. Date:

04/05/2017

Chassis No:

RU11205190

NO

air (day) 0

*Not Notified
Call 83100
Runny After Paint 5 days*

I WAS DRIVING ALONG CLIVE STREET WHEN M/LORRY GBB5256L SUDDEN DASH OUT FROM DUNLOP STREET AND HIT ONTO THE FRONT RH PORTION OF MY CAR. NO ONE WAS INJURED.

VEHICLE SENT INTO ANG MO KIO WORKSHOP ON 15/06/2020

CHENG HOE MOTOR PTE LTD (AMK)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

DORLYN LI YAZHU

Amount

2,704.00

150.00

1,620.00

0.00

0.00

Gross Total (S\$)

4,474.00

+ GST 7.00% (S\$)

313.18

Nett Amount (S\$)

4,787.18

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REF: FC2/20006445/1K2

TAILS

AILS

Version: 1.0 (Last Synchronised: 16 Jun 2020)
 HONDA VEZEL 1.5 (A) (Catalogue:Merimen Singapore 1.0)
 (Price-denominated Standard List)

Code: Cheng Hoe Motor Pte Ltd/SLN2882S/16/06/2020 11:03

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

Part No.	Particulars	%Disc	%Depr	Amount
*1 pc front RH fender	By	0.00	0.00	*190.00 F
*1 pc front RH fender inner shield	CM	0.00	0.00	*80.00 F
*6 pcs front RH fender inner shield clips @ \$2/pc	By	0.00	0.00	*12.00 F
*1 pc front RH fender wheel arch garnish	By	0.00	0.00	*55.00 F
*1 pc RH headlamp	mg CM	0.00	0.00	*830.00 FL
*1 pc front RH door	By	0.00	0.00	*530.00 FL
*1 pc front RH door frame sticker	By	0.00	0.00	*12.00 F
*1 pc front RH door checker	By	0.00	0.00	*40.00 F
*1 pc front RH door top hinge	By	0.00	0.00	*30.00 F
*1 pc front RH door side mirror outer cover	By	0.00	0.00	*60.00 F
*1 pc front RH rim	By	0.00	0.00	*350.00 F
*1 pc front RH shock absorber	By	0.00	0.00	*220.00 F
*1 pc front RH knuckle arm	By	0.00	0.00	*195.00 F
*1 pc front RH wheel bearing	By	0.00	0.00	*100.00 F
Total Parts (S\$)				2,704.00

Cheng Hoe Motor Pte Ltd/SLN2882S/16/06/2020 11:03. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Items	Amount
front sun shade	120.00
	150.00
Sub Total (S\$)	150.00

Estimates on Labour

Lab.Type	Amount
fix front bumper & attachments, headlamps, frt RH fender, frt RH door & attachments; knocking	500.00
frt RH fender inner panel & realign bonnet the same	600.00
fix front bumper, front RH fender & inner panel, frt RH door, RH side mirror & all affected areas	650.00
fix front RH door window glass & reset central locking	50.00
fix front RH wheel, undercarriage & realign the same	90.00
computer wheel alignment	60.00
	60.00
Gross Labour Cost (S\$)	1,620.00

Cheng Hoe Motor Pte Ltd/SLN2882S/16/06/2020 11:03. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >