

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

From: LKK Auto Consultants Pte Ltd
 51 Ubi Ave 1 #01-25
 Paya Ubi Industrial Park
 Singapore 408933

Attn: Adeline Chng Pei Wen Date: 20 Jul 2020

Preliminary Advice

Insured Vehicle No	:	GBB5256L		
TP Vehicle No	:	SLN2882S	Accident Date	: 15/06/2020
Make	:	HONDA VEZEL	Assignment Date	: 16/06/2020
Date of Inspection	:	16/06/2020	Est. Duration of Repair	: 5
Inspection At	:	CHENG HOE MOTOR PTE LTD (YISHUN) BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A SINGAPORE 768761		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:	S\$ 4,474.00
Revised Amount	:	S\$ 3,899.00
Check Items (Estimated)	:	S\$ 0.00
Total	:	S\$ 3,899.00
Lump Sum Repair		S\$ 3,100.00

Total Loss Consideration

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :