

Hsing Long

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48 AUTOBAY
SINGAPORE 417883

Not Authorized
16/6/20
2/5 @ 4500/
Hsing.

VEHICLE No: SJM 8569L

1PC	REAR WINDSCREEN MOULDING		rec	\$68.10	✓
1PC	TAILGATE	785.20	DO	\$845.20	✓
1PC	TAILGATE FIT EMBLEM		rec	\$45.00	✓
1PC	TAILGATE INNER LOCK	197.40	should	\$209.60	✓
1PC	TAILGATE INNER TRIM	241.20	De/Torn	\$388.20	✓
1PC	TAILGATE WEATHERSTRIP	145.60	Tru	\$166.80	✓
1PC	REAR BUMPER	497.40	DO	\$645.50	✓
2PCS	REAR BUMPER SIDE RETAINERS @ \$30.50		o/s Bent	\$61.00	PC
1PC	REAR BUMPER BRACKET		Scr	\$145.00	X
1PC	REAR END PANEL	316.20	no/surf	\$366.00	✓
1PC	REAR END PANEL TOP GARNISH		11	\$219.00	X
2PCS	TAILLAMPS @ \$485.00	288.20	o/s crn	\$970.00	IPC
2PCS	TAILLAMP HOUSING PANELS @ \$288.50		11	\$577.00	X
1PC	REAR FENDER		11	\$911.20	X
1PC	REAR FENDER INNER TRIM		11	\$388.50	X
1PC	REAR AIR VENT		crn	\$45.00	✓
1PC	REAR FLOOR PANEL		11	\$911.00	X
1PC	REAR FLOOR PANEL TOP BOARD		11	\$388.50	X
				\$7,350.60	
1PC	REAR WINDSCREEN SEALANT		rec	\$50.00	40
1SET	TAILGATE INNER TRIM CLIPS		rec	\$40.00	✓
1PC	REAR BUMPER LOWER SKIRTING		ref/cr	\$1,200.00	950
1SET	REAR BUMPER REVERSE SENSOR		should	\$280.00	200
1SET	REAR BUMPER CLIPS		rec	\$40.00	✓
1SET	REAR BUMPER REFLECTOR		scr	\$120.00	60
1PC	REAR END PANEL SEALANT		rec	\$50.00	✓
1PC	TAILGATE OUTER GARNISH		scr	\$250.00	160
				\$50.00	20
				\$80.00	50
				\$120.00	80
				\$100.00	60
				\$150.00	120
				\$100.00	50
				\$1,500.00	600
				\$1,500.00	1000
				\$12,980.60	

LKK Auto Consultants hence notify the Repairer of the following: TOTAL

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-2659.80
20%
P-2127.84
S-1540
17980
5347