



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMB 3056E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	NS SIDE PANEL L11 (PSV)	REPAIRED SEE LABOUR	720.00	-
1	NS ENGINE FRAME LAST	REPAIRED SEE LABOUR	560.00	-
1	SIKAFLEX BLACK	NOT NECESSARY	32.00	-
			1,312.00	-
<b><u>LABOUR</u></b>				
	TO DISMANTLE & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF NS SIDE PANEL L11 (PSV) AND NS ENGINE FRAME LAST. SPRAY PAINTING.		1,950.00	650.00
			1,280.00	640.00
			3,230.00	1,290.00
<b>GRAND TOTAL</b>			<b>4,542.00</b>	<b>1,290.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,290.00</b>

Report Ref No. CS/AWA20006336/R1qf3e2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.