

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 37006

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0422/2020/NS
Date : 10-Jun-20

Dense

Vehicle IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Wong Sok Yee
Address : 62 Lengkong Tiga
#05-07
Singapore 417455
Telephone : HP +65 98556066
Type of Claim : Own Damage Claims
Policy No. : 1800149392-01
Vehicle No : **SMG 3190 Z**
Model Code : Audi A3 Sedan 1.4 TFSI CO
Model / Year : Dec-18
Engine No : CZE 846765
Chassis No : WAUZZZ8V2K1007852
Mileage : 28683Km
Date In : 9/6/2020
Estimated By : Johnny Boo / Allan Wu
Accident Date : 9-Jun-20
Place of Accident : Jln Eunos And Eunos Crescent Cross Junction

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 7323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMG 3190 Z

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00	✓ ✓
2	To remove and renew aircon condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00	✓ ✓
3	To dismantle rhs front door panel trim. To remove and reinstall rhs wing mirror assy.	S/N \$ 350.00 280	✓
4	To dismantle and renew front bumper, rhs front fender, bonnet, and rhs headlight. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 5,250.00 3000	✓
5	To respray front bumper, rhs front fender, bonnet hinges, rhs front door and rhs upper A-pillar. Bonnet ✓	\$ 4,900.00 $4.5 \times 550 = 2475$	✓
6	To carry out pre-diagnostic check and post-diagnostic check.	S/N \$ 384.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 12,444.00	

Premium Automobiles

55, 56, Road 1, Singapore 408659
Tel: 6356 2221 Fax: 6341 1181

Telefax

Material List for Accident Vehicle Regn No. SMG 3190 Z

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Distorted</i>	\$ 1,894.00	✓ 1589.6
2	FRONT BUMPER FIXING PARTS <i>all new</i>	\$ 176.00	+
3	FRONT BUMPER GUIDE SECTION - RH <i>new</i>	\$ 36.00	✓ 30.16
4	FRONT BUMPER GRILLE - CENTRE <i>could</i>	\$ 151.00	✓ 126.8
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>could</i>	\$ 505.00	✓ 424.00
6	FRONT BUMPER CLOSING ELEMENT - RH <i>new</i>	\$ 280.00	✓ 234.4
7	FRONT BUMPER COVER TRIM- RH <i>missing</i>	\$ 153.00	✓ 128.4
8	WHEEL HOUSING LINER ADAPTER - RH <i>new</i>	\$ 36.00	✓ 29.52
9	RADIATOR GRILLE <i>could</i>	\$ 1,338.00	✓ 1124.8
10	RADIATOR GRILLE CLOSING ELEMENT <i>could</i>	\$ 180.00	✓ 150.8
11	FRONT BUMPER AIR GUIDE GRILLE - RH <i>missing</i>	\$ 177.00	✓ 148.4
12	AIRCON STICKER <i>for</i>	NEC \$ 7.00	✓ 5.68
13	CAUTION SIGN STICKER	NEC \$ 13.00	✓ 10.80
14	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>best</i>	\$ 681.00	✓ 571.60
15	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	\$ 178.00	✓ 149.6
16	FRONT BUMPER FOAM FILLER PIECE COVER <i>could</i>	\$ 115.00	✓ 96.4
17	SIGNAL HORN - RH LOW TONE <i>new</i>	\$ 188.00	✗
18	FRONT FENDER - RH <i>Buckeed</i>	\$ 802.00	✓ 672.8
19	FRONT FENDER ATTACHMENT PARTS <i>new new</i>	\$ 68.00	✗
20	FRONT FENDER BRACKET - RH <i>Best</i>	\$ 26.00	✓ 21.52
SUB TOTAL SPARE PARTS CHARGES		\$ 7,004.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408696
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 3190 Z

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
21	FRONT FENDER BRACKET - RH <i>Bent</i>	\$ 36.00	✓ 30.4
22	FRONT FENDER BRACE <i>Bent</i>	\$ 90.00	✓ 75.68
23	FRONT FENDER CLOSING ELEMENT - RH <i>Not new</i>	\$ 31.00	X
24	FRONT FENDER INSULATION - RH <i>new</i>	\$ 40.00	+
25	WHEEL HOUSING LINER SEAL - RH <i>Not new</i>	\$ 32.00	X
26	WHEEL HOUSING LINER - RH <i>for</i>	\$ 159.00	— 133.2
27	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not new</i>	\$ 84.00	X
28	BONNET <i>Dented</i>	\$ 2,988.00	✓ 2507.2
29	BONNET ATTACHMENT PARTS <i>Not new</i>	\$ 155.00	X
30	BONNET LID HINGE - LH / RH <i>Not new RH Bent</i>	2 \$ 116.00	X 48.24
31	BONNET GAS FILLED STRUT <i>Not new</i>	\$ 112.00	+
32	BONNET CATCH HOOK <i>new</i>	\$ 84.00	+
33	BONNET STRIKER - LH / RH <i>Not new</i>	2 \$ 208.00	X
34	BONNET EDGE PROTECTION <i>new</i>	\$ 26.00	— 21.84
35	INNER FENDER COVER - RH <i>new</i>	\$ 39.00	+
36	BONNET LID LOCK <i>Not new</i>	2 \$ 403.00	X
37	BONNET BOWDEN CABLE - CENTRE <i>new</i>	\$ 54.00	+
38	BONNET LID LOCK CABLE <i>new</i>	\$ 69.00	+
39	BONNET SOUND ABSORBER <i>new</i>	\$ 207.00	+
40	PLENUM CHAMBER COVER <i>Not new</i>	\$ 169.00	+
SUB TOTAL SPARE PARTS CHARGES		: \$ 5,102.00	

Premium Automobiles

55, 018, Road 1, Singapore 416619
Tel: 6396 2121 Fax: 6394 1181

Telefax

Material List for Accident Vehicle Regn No. SMG 3190 Z

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
41	LED HEADLIGHT - RH <i>cracked</i>	S	5,193.00 ✓ 4364
42	MAIN LIGHT ELECTRONICS POWER MODULE - RH <i>new</i>	S	714.00 ✗
43	LED WITH HEAT SINK - RH <i>new</i>	S	689.00 ✗
44	LIGHT CONTROL SYSTEM CONTROL UNIT <i>new</i>	S	524.00 ✗
45	HEADLIGHT HOSE - RH <i>all n</i>	S	38.00 ✗
46	HEADLAMP REPAIR KIT <i>new</i>	S	124.00 ✗
47	LIFT CYLINDER - LH / RH <i>RH cracked</i>	2 S	268.00 134.112.4
48	LIFT CYLINDER HOSE <i>new cut</i>	S	64.00 ✓ 53.2
49	LOCK CARRIER <i>cracked</i>	S	685.00 ✓ 575.2
50	AIRCON CONDENSER <i>Bent</i>	S	519.00 ✓ 436.00
51	REFRIGERANT LINE <i>Bent</i>	S	613.00 ✓ 495.2
52	REFRIGERANT LINE <i>Bent</i>	S	471.00 ✓ 380.40
53	RADIATOR <i>distorted</i>	S	932.00 ✓ 752.80
54	ADDITIONAL RADIATOR <i>distorted</i>	S	851.00 ✓ 687.20
55	RADIATOR SEALING STRIP <i>new</i>	S	15.00 ✗
56	RADIATOR BRACKET <i>distorted</i>	2 S	78.00 ✓ 62.88
57	RADIATOR BUSH - LOWER <i>new</i>	2 S	19.00 ✗
58	READY MIX COOLANT <i>new</i>	4 S	169.00 ✓ 141.44
59	RADIATOR FAN <i>new</i>	S	1,091.00 ✗
60	RADIATOR AIR GUIDE - RH <i>distorted</i>	S	23.00 ✓ 19.2
61	RADIATOR AIR GUIDE - UPPER CENTRE <i>new</i>	S	12.00 ✗
62	FRONT NO PLATE <i>dented</i>	S/N S	60.00 ✓ 60.00
63	SUNDRIES <i>new</i>	S	500.00 ✓ 26.72
TOTAL SPARE PARTS CHARGES		:	\$ 25,758.00
TOTAL LABOUR CHARGES		:	\$ 12,444.00
GRAND TOTAL		:	\$ 38,202.00

All charges are not inclusive of GST.

Legend Remarks (OK) - Approved, Remarks (X) - Not approved
Spare parts are Special Nett

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0422/2020/NS 18-Jun-20 Glory Tan 1 of 1 SMG 3190 Z Audi A3 Sedan 1.4 TFSI CO
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To place the vehicle on cellette bench to realign rhs front bumper chassis frame.	s/n \$ 1,200.00	\$ 1,200.00 ✓
2	To respray front bumper rhs chassis frame.	\$ 700.00	\$ 550.00 ✓
TOTAL		\$ 1,900.00	\$ 1,750.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. PA/OD/0422/2020/NS Date 12-Jun-20 Service Advisor Glory Tan Pages 1 of 1 Regn No SMG 3190 Z Model No Audi A3 Sedan 1.4 TFSI CO	
Quantity	Description	Unit Price	Amount
Parts			
1	Noise insulation underbody <i>torn</i>	\$ 244.00	\$ 217.20 ✓
2	Wheel housing liner front LHS <i>del</i>	\$ 159.00	\$ 133.20 ✓
3	Coolant hose with quick release coupling <i>del</i>	\$ 58.00	\$ 48.08 ✓
4	Temperature sensor bracket <i>del</i>	\$ 18.00	\$ 14.40 ✓
5	Front bumper cover trim LHS <i>del</i>	\$ 153.00	\$ 128.40 ✓
6	Bonnet catch hook <i>del</i>	\$ 60.00	\$ 49.76 ✓
7	Wheel housing liner adapter LHS <i>del</i>	\$ 36.00	\$ 29.52 ✓
			\$ 620.56
Labours			
1	To respray rhs sill panel.	\$ 900.00	\$ 550.00 ✓
TOTAL		\$ 1,628.00	\$ 1,170.56

For Premium Automobiles Pte Ltd

 Authorised Signature

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0422/2020/NS 22-Jun-20 Glory Tan 1 of 1 SMG 3190 Z Audi A3 Sedan 1.4 TFSI CO
Quantity	Description	Unit Price	Amount
<u>Parts</u> 1	Front windscreen water deflector strip LHS <i>cut</i>	\$ 87.00	\$ 72.88
TOTAL		\$ 87.00	\$ 72.88

For Premium Automobiles Pte Ltd

Authorised Signature

premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Adnan Ling
10/06/20

Not Authorised, ~~10~~ Days

11 Days
H.S.

Please Note :

This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khan at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: