

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0422/2020/NS

12-Jun-20

Glory Tan

1 of 1

SMG 3190 Z

Audi A3 Sedan 1.4 TFSI CO

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Noise insulation underbody <i>ca</i>	\$ 244.00	
2	Wheel housing liner front LHS <i>ca</i>	\$ 159.00	
3	Coolant hose with quick release coupling <i>cut</i>	\$ 58.00	
4	Temperature sensor bracket <i>cut</i>	\$ 18.00	
5	Front bumper cover trim LHS <i>ca</i>	\$ 153.00	
6	Bonnet catch hook <i>bt</i>	\$ 60.00	
7	Wheel housing liner adapter LHS <i>re</i>	\$ 36.00	
<u>Labours</u>			
1	To respray rhs sill panel.	\$ 900.00	<i>550</i>
TOTAL		\$ 1,628.00	

For Premium Automobiles Pte Ltd

Paul
15/06/2020

Authorised Signature

*Subject to insurance
approval
EXTRA 1 days*

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 3190 Z

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
1	FRONT BUMPER <i>Distorted</i>	\$ 1,894.00	✓
2	FRONT BUMPER FIXING PARTS <i>Dist</i>	\$ 176.00	✓
3	FRONT BUMPER GUIDE SECTION - RH <i>Rec</i>	\$ 36.00	✓
4	FRONT BUMPER GRILLE - CENTRE <i>could</i>	\$ 151.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>could</i>	\$ 505.00	✓
6	FRONT BUMPER CLOSING ELEMENT - RH <i>Dist</i>	\$ 280.00	✓
7	FRONT BUMPER COVER TRIM- RH <i>Missing</i>	\$ 153.00	✓
8	WHEEL HOUSING LINER ADAPTER - RH <i>Dist</i>	\$ 36.00	✓
9	RADIATOR GRILLE <i>could</i>	\$ 1,338.00	✓
10	RADIATOR GRILLE CLOSING ELEMENT <i>can</i>	\$ 180.00	?
11	FRONT BUMPER AIR GUIDE GRILLE - RH <i>Missing</i>	\$ 177.00	✓
12	AIRCON STICKER <i>3</i>	NEC \$ 7.00	✓
13	CAUTION SIGN STICKER <i>1</i>	NEC \$ 13.00	✓
14	FRONT BUMPER SIDE REINFORCEMENT BEAM <i>best</i>	\$ 681.00	✓
15	FRONT BUMPER FOAM FILLER PIECE <i>could</i>	\$ 178.00	✓
16	FRONT BUMPER FOAM FILLER PIECE COVER <i>could</i>	\$ 115.00	✓
17	SIGNAL HORN - RH LOW TONE <i>Not on</i>	\$ 188.00	X
18	FRONT FENDER - RH <i>Buckeed</i>	\$ 802.00	✓
19	FRONT FENDER ATTACHMENT PARTS <i>?</i>	\$ 68.00	?
20	FRONT FENDER BRACKET - RH <i>2 4</i>	\$ 26.00	?
SUB TOTAL SPARE PARTS CHARGES		: \$ 7,004.00	

Premium Automobiles

55, Ulu Road 1, Singapore 408699
Tel: 65-6-2323 Fax: 65-411183

Telefax

Material List for Accident Vehicle Regn No. SMG 3190 Z

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
2	FRONT FENDER BRACKET - RH <i>? bt ✓</i>	\$ 36.00	?
22	FRONT FENDER BRACE <i>? bt ✓</i>	\$ 90.00	?
23	FRONT FENDER CLOSING ELEMENT - RH <i>?</i>	\$ 31.00	?
24	FRONT FENDER INSULATION - RH <i>new</i>	\$ 40.00	+
25	WHEEL HOUSING LINER SEAL - RH <i>torn ?</i>	\$ 32.00	+ ?
26	WHEEL HOUSING LINER - RH <i>torn</i>	\$ 159.00	✓
27	WHEEL HOUSING LINER ATTACHMENT PARTS <i>?</i>	\$ 84.00	?
28	BONNET <i>Dented</i>	\$ 2,988.00	✓
29	BONNET ATTACHMENT PARTS <i>?</i>	\$ 155.00	?
30	BONNET LID HINGE - LH / RH <i>all in bt ✓</i>	2 \$ 116.00	X
31	BONNET GAS FILLED STRUT <i>all in</i>	\$ 112.00	+
32	BONNET CATCH HOOK <i>all in X</i>	\$ 84.00	+
33	BONNET STRIKER - LH / RH <i>?</i>	2 \$ 208.00	?
34	BONNET EDGE PROTECTION <i>new</i>	\$ 26.00	✓
35	INNER FENDER COVER - RH <i>all in</i>	\$ 39.00	+
36	BONNET LID LOCK <i>?</i>	2 \$ 403.00	?
37	BONNET BOWDEN CABLE - CENTRE <i>new</i>	\$ 54.00	+
38	BONNET LID LOCK CABLE <i>all in</i>	\$ 69.00	+
39	BONNET SOUND ABSORBER <i>all in</i>	\$ 207.00	+
40	PLENUM CHAMBER COVER <i>all in</i>	\$ 169.00	+
SUB TOTAL SPARE PARTS CHARGES		: \$ 5,102.00	

Premium Automobiles

65 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMG 3190 Z

S/N	Parts Description	Damage Parts & Prices	
		S/Nett	Remarks
41	LED HEADLIGHT - RH <i>cracked</i>	\$ 5,193.00	✓
42	MAIN LIGHT ELECTRONICS POWER MODULE - RH ?	\$ 714.00	?
43	LED WITH HEAT SINK - RH ?	\$ 689.00	?
44	LIGHT CONTROL SYSTEM CONTROL UNIT ?	\$ 524.00	?
45	HEADLIGHT HOSE - RH <i>new</i>	\$ 38.00	x
46	HEADLAMP REPAIR KIT ?	\$ 124.00	?
47	LIFT CYLINDER - LH / RH <i>RH cracked</i>	2 \$ 268.00	134
48	LIFT CYLINDER HOSE <i>new cut</i>	\$ 64.00	+
49	LOCK CARRIER <i>cracked</i>	\$ 685.00	✓
50	AIRCON CONDENSER <i>> bt</i>	\$ 519.00	?
51	REFRIGERANT LINE <i>> bt</i>	\$ 613.00	?
52	REFRIGERANT LINE <i>? bt</i>	\$ 471.00	?
53	RADIATOR <i>? bt</i>	\$ 932.00	?
54	ADDITIONAL RADIATOR <i>> bt</i>	\$ 851.00	?
55	RADIATOR SEALING STRIP ?	\$ 15.00	?
56	RADIATOR BRACKET <i>? new</i>	2 \$ 78.00	?
57	RADIATOR BUSH - LOWER ?	2 \$ 19.00	?
58	READY MIX COOLANT <i>new</i>	4 \$ 169.00	✓
59	RADIATOR FAN <i>new</i>	\$ 1,091.00	x
60	RADIATOR AIR GUIDE - RH <i>Damaged</i>	\$ 23.00	✓
61	RADIATOR AIR GUIDE - UPPER CENTRE ?	\$ 12.00	?
62	FRONT NO PLATE <i>Dented</i>	S/N \$ 60.00	✓
63	SUNDRIES ?	\$ 500.00	?
TOTAL SPARE PARTS CHARGES		: \$ 25,758.00	
TOTAL LABOUR CHARGES		: \$ 12,444.00	
GRAND TOTAL		: <u>\$ 38,202.00</u>	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.