

## View Sent Message

This mail is associated with :

**\*SMG3190Z (5972569338SG)**  
OD  
Jun 9 2020 12:00PM  
[WONG SOK YEE]  
Premium Automobiles Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on 19/06/2020 17:14 PM.

**To** Victor-CK.Koh@aig.com

**CC** denisetay@lkkauto.com

**Subject** Re: Alert - Adj Mandate Approved (S\$24956.00) - SMG3190Z - Claim Handler: Nadaraja, Deeban

Dear Victor,

During the initial survey, it can be seen that the front RH fender was already displaced due to the impact, which also signifies that there could be a possibility of a misaligned sill panel (see photos 25- 30)

After dismantling, a slight buckle was observed at the frontal portion of the sill panel and hence a repair and spray painting was recommended for the sill panel (see photo 81- 85)

Hope that the above clarifies matter.

Regards,  
Denise on behalf of Adrian  
LKK auto

<-- Original Message -->

From: AIG\_SG

To: LKK\_HQ

Sent On: 18/06/2020 11:43 AM

Subject: Alert - Adj Mandate Approved (S\$24956.00) - SMG3190Z - Claim Handler: Nadaraja, Deeban

Approved:24956.00:RESPRAY RHS SILL PANEL not necessary to take out.

### DOCUMENTS SUMMARY

There are no documents.

