

COMFORTDELGRO PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC85765

14/06/20

MAKE :

CHIANG/QRM QSE

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER SIDE BRACKET RH /LH		\$55.80 \$111.60
10	REAR BUMPER CLIPS		\$22.00
1	REAR BUMPER REINFORCEMENT		\$294.80
1	REAR BUMPER REINFORCEMENT BRACKET		\$138.10 \$276.20
1	REAR BUMPER LOWER MOULDING		\$155.00
1	REAR BUMPER FOG LAMP		\$201.50
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	BOOT LID		\$2,480.40
1	BOOT LID GLASS UPPER		\$543.30
1	BOOT LID GLASS LOWER		\$384.90
1	EMBLEM- IONIQ		\$31.30
1	BOOT LID HYBRID PLATE		\$24.30
1	BOOTLID H EMBLEM		\$28.00
1	REAR BUMPER REFLECTOR RH		\$31.90
1	REAR BUMPER TOW COVER		\$98.80
	SUB TOTAL		\$5,594.65
	25.00%		\$1,118.93
	DISCOUNTED TOTAL		\$4,195.98
1	REAR NUMBER PLATE/W HOLDER		\$50.00
1	REAR REVERSE SENSOR		\$180.00
1	COMFORT LOGO STICKER		\$30.00
1	TEL NUMBER STICKER		\$30.00
			\$290.00
	Labour Charge		
	Panel Beating		\$1,020.00
	Spray Painting Charge		\$500.00
	Check wiring		\$60.00
	Tuff Kote		\$60.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$1,700.00
	ESTIMATE TOTAL		\$6,185.98

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tanfikh 93495749
15/6/20 @ 415pm
p/p Resurvey before paint
03 days
tanfikh@lkkauto.com.

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road, Singapore 571201
Mainline : 65 6343 6280 Facsimile : 65 6280 9755

Workshops

59 Luyang Drive Singapore 508969 24 Serangoon Road Singapore 758136
383 Sin Ming Drive Singapore 575717 7 Serangoon Road Singapore 758137
45 Pandan Road Singapore 600796 501 Pandan Road Singapore 600796

Date/Time: 15.06.2020 10:57

Page : 1

Team: ARC Repair TP(CLS0)1

JOB CARD Sales Order:

JC NO: 305404972


STOMER	REGN NO: SHC8576S	MILEAGE
/MS COMFORT TRANSPORTATION PTE LTD	MAKE: HYUNDAI	FUEL
STOMER NO 7010045	MODEL IONIQ(G2)	DATE/TIME IN 14.06.2020 18:45
DRESS 383 SIN MING DRIVE	YR OF MANU 01.08.2019	TARGET DATE
Singapore SINGAPORE 575717	CHASSIS CODE KMHC851CVKU165112	COMPLETION DATE/TIME
65508755		
(R)		
(P)		
COUNT CARD NO.		

JOB DESCRIPTION

Accident Date: 14.06.2020

NATURE: 3P 14.06.202

S/NO LABOR CODE DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No: SHC8576S

CHIANG

Vehicle No.: SHC8576S

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard