



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC6/AXA15001299/Kza3s2

8 SHENTON WAY #27-01 SINGAPORE 068811

Date : 17-12-2015



ATTN: STACEY NG

Code : AXA2

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GZ 1493J	Veh. Inspected	SKP 3515Y
Policy No.	P1560685	Coverage (\$)	0.00
Claim No.	C0328493	Excess (\$)	0.00
Assign From		Assign Date	21/01/2015

#### 2. Vehicle Particulars & Condition

Make & Model	HONDA JAZZ (A)	c.c	1318
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JHMGK3850FX200202	Colour	METALLIC SILVER
Odometer	15237	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/65R15	DUNLOP	8 mm
L/H Front Tyre	175/65R15	DUNLOP	8 mm
R/H Rear Tyre	175/65R15	DUNLOP	8 mm
L/H Rear Tyre	175/65R15	DUNLOP	8 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	20/01/2015	Inspection Date	21/01/2015
Survey held at	K KIM HIN AUTO PTE LTD BLK 34 SIN MING DRIVE, #01-114, SINGAPORE 575708		

#### 5a. Remarks

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	1 Working Days
-------------------------------------	----------------



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKP 3515Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>LABOUR</u></b>			
	TO REMOVE, CUT OUT DAMAGED PARTS, PANEL BEATING, WELDING , ALIGN, REFIX AND TO RENEW AFFECTED PARTS.		120.00	60.00
	TO PUTTY AND RESPRAY ON AFFECTED PORTIONS.		200.00	180.00
			320.00	240.00
<b>GRAND TOTAL</b>			<b>320.00</b>	<b>240.00</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>240.00</b>

Report Ref No. CC6/AXA15001299/Kza3s2

**KONG SENG CHEONG**

**Licensed Appraiser**

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.