



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司
新民通道 (大牌 34 座) 門牌 114 號
Blk 34 Sin Ming Drive, #01-114, Singapore 575708.
Tel: 6452 7018 (5 Lines) Fax: 6458 3895
Email: service@kkinhin.com.sg

No. : 26668

Vehicle Insured : GZ 1493 J
Accident Date : 20-Jan-2015

Date : 21-Jan-2015

Our Ref : 150048 (AXA) / XW

PAGE : 1

BUKIT BATOK DRIVING CENTRE LTD
Singapore

Not Attached
1 day 1-B.1 824ch

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.3 CVT ABS (2014) SKP3515Y
=====

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

120.00 *601*

To putty and respray on affected
portions.

200.00 *1801*

Total : S\$ 320.00
=====

Singapore Dollars Three Hundred and Twenty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: