



AUTOPIE LTD

金興(龔)汽車私人有限公司

新民通道 (大牌 34 座) 門牌 114 號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

No. : 26668

Vehicle Insured : GZ 1493 J

Accident Date : 20-Jan-2015

Date : 21-Jan-2015

Our Ref : 150048 (AXA) / XW

PAGE : 1

BUKIT BATOK DRIVING CENTRE LTD
Singapore

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.3 CVT ABS (2014) SKP3515Y

To remove, cut out damaged parts,
panel beating, welding, align,
refix and to renew affected parts.

120.00

To putty and respray on affected
portions.

200.00

Total : S\$ 320.00

Singapore Dollars Three Hundred and Twenty Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.