



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

新民通道(大牌34座)門牌114號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

No. : 26677

Vehicle Insured : SJQ 8835 Y

Accident Date : 25-Jan-2015

Date : 27-Jan-2015

Our Ref : 150056 (AXA) / XW

PAGE : 1

BUKIT BATOK DRIVING CENTRE LTD
Singapore

ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.3L MT (2012) SKF6321Y

1 pc	tailgate	Bu	680.20	✓
1 pc	tailgate "jazz" emblem	sn	26.20	✓
1 pc	tailgate glass moulding - lower	sn	42.00	✓
1 pc	tailgate glass moulding - top	sn	46.00	✓
1 pc	rear bumper	Bu	440.50	✓
1 pc	n/s rear bumper side retainer	Dir	18.00	✓
8 pcs	rear bumper clips	sn	48.00	✓
			@ S\$ 6.00	
			1,300.90	
			Less 20% :	-260.18
			1,040.72	
1 pc	tailgate "thanks for your patience" sticker	sn	150.00	✓
1 pc	tailgate "8" reflective sticker	sn	5.00	✓
1 pc	tailgate glass sealant	sn	40.00	✓
1 pc	tailgate glass damping seal	sn	20.00	✓
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.			480.00	400
To putty and respray on affected portions.			600.00	400
To apply undersealing.			30.00	✓

Con't Page 2 ...



CO. REG. NO: 199402370D
GST NO: M2-0123250-3

AUTO PTE LTD

金興(龔)汽車私人有限公司

新民通道(大牌34座)門牌114號

Blk 34 Sin Ming Drive, #01-114, Singapore 575708.

Tel: 6452 7018 (5 Lines) Fax: 6458 3895

Email: service@kkinhin.com.sg

Vehicle Insured : SJQ 8835 Y
Our Ref : 150056

Page : 2
No. : 26677

To remove and renew rear windscreen
glass and conduct water leak test.

120.00 ✓

To transfer tailgate's fittings.

80.00 602

Total : S\$ 2,565.72
=====

Singapore Dollars Two Thousand Five Hundred and
Sixty Five and Cents Seventy Two Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.