

KIAN TEONG AUTO CENTRE

Blk 176 Sin Ming Drive #01-08

Sin Ming AutoCare Singapore 575721

Tel No. : 64556268 Fax No. : 64555166

E-Mail : info@ktauto.com.sg

Website : www.ktauto.com.sg

Tax Reg. No. : 52991859E Buss. Reg. No. : 52991859E

AIG ASIA PACIFIC INSURANCE PTE LTD

Estimate : ES000431

Date : 11/06/2020

Vehicle Num. : SKE 7295 M

Make/Model : TOYOTA CAMRY 2.0-2006

Chassis/Eng# : MR053BK4107004735/1AZE017066

Accident Date : 11/06/2020

Claim No. :

Reference :

Policy No. :

Attention : Motor Claim Department

Contact : 64193000 Fax No. : 64153727

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	REAR BOOTH x repair		980.00 X
2.	1	REAR END PANEL x repair		448.00 X
3.	1	REAR BUMPER REINFORCEMENT ✓ BT		495.00 361.8
4.	1	REAR BUMPER ✓ DE		778.50 566.2
5.	1	REAR BOOTH LOCK x NN		165.00 X
6.	1	REAR BOOTH LATCH x NN		98.00 X
7.	1	REAR BOOTH EMBLEM (CAMRY) ✓ NEC		48.70 36.9
8.	1	REAR BOOTH EMBLEM (TOYOTA LOGO) ✓ NEC		46.70 30.7
9.	2.0	REAR BOOTH EMBLEM ✓ NEC	45.00	90.00 35
List Total S\$:			1030.6	3,149.90
			-25%: 772.95	
NETT ITEMS :				
1.	1 SET	REAR BUMPER REVERSE SENSOR ✓ DM		150 220.00
Nett Total S\$:				220.00
LABOUR :				
LABOUR FEES:				
TO SPRAY PAINT ALL DAMAGED PARTS				580.00 500
TO REMOVE AND CHANGE ALL DAMAGED PARTS				480.00 400
TO KNOCK AND RE-ALIGN ALL DAMAGED PARTS				
TO CHECK REAR TAIL LAMP AND SENSOR WIRING				100.00 40
Labour Total S\$:				1,160.00 940

E. & O.E.

Total S\$: 4,529.90

1862.95

-20%: 1500

4 days

Please do not hesitate to contact us at the above number if there is any other further quire.
We thank you for your kind attention. Your prompt reply is greatly appreciated.

for KIAN TEONG AUTO CENTRE



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: