



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD  
36 ROBINSON ROAD  
#16-01 CITY HOUSE  
SINGAPORE 068877

INV No. AC2006097  
INV Date 07/09/2020  
Reference CC3/FCI20006346/Kda3q2  
Code FCI2



#### PROFESSIONAL SERVICE FEE

Vehicle No. SHD 9418D  
Insured Veh. SHD 8577J  
Claim No. D20002447MFSH  
Policy No. D-18088937MFSH  
Accident Date 12/06/2020  
Inspection Date 16/06/2020

Description	Total
Third Party Express Settlement	350.00
<b>Subtotal</b>	<b>350.00</b>
<b>GST (7%)</b>	<b>24.50</b>
<b>Grand Total</b>	<b>374.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MS FIRST CAPITAL INSURANCE LTD		Ref : CC3/FCI20006346/Kda3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 07-09-2020	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 8577J	Veh. Inspected	SHD 9418D
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D20002447MFSH	Excess (\$)	0.00
Assign From		Assign Date	16/06/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS (A)	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	JTDKB3FU303082903	Colour	M. P. WHITE / RED
Odometer	62200	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	SAILUN	9 mm
L/H Front Tyre	195/65 R15	SAILUN	9 mm
R/H Rear Tyre	195/65 R15	SAILUN	9 mm
L/H Rear Tyre	195/65 R15	SAILUN	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/06/2020	Inspection Date	16/06/2020
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>2 Working Days</b>	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 9418D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	MOULDING ASSY ,BODY ROCKER PANEL ,RH	SERVICEABLE	594.80	-
1	PANEL SUB-ASSY ,QUARTER ,RH	TO REPAIR SEE LABOUR	871.50	-
1	REAR FENDER LINER	SERVICEABLE	139.80	-
1	DUCT ASSY ,QUARTER VENT , RH	SERVICEABLE	67.00	-
1	SEAL ,REAR BUMPER SIDE ,RH	SERVICEABLE	88.50	-
1	REAR BUMPER	BUCKLED / DENTED	442.60	442.60
1	REAR BUMPER UNDER COVER (BLACK)	SERVICEABLE	576.30	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	117.70	-
1	COVER ,FLOOR UNDER ,RH	SERVICEABLE	175.10	-
1	TAILLAMP LOWER RH	SERVICEABLE	502.00	-
1	TAILLAMP UPPER RH	SERVICEABLE	451.80	-
1	REAR BUMPER SIDE RH	SERVICEABLE	123.70	-
1	REAR WHEEL RIM	SERVICEABLE	1,879.40	-
1	REAR WHEEL RIM COVER	SERVICEABLE	211.50	-
	LESS 25% DISCOUNT		-1,560.43	-110.65
			4,681.27	331.95
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REAR BUMPER CLIP (SN)	NECESSARY	68.00	68.00
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	140.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	180.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	120.00	-
1	SET REAR FENDER LINER CLIP (SN)	NOT NECESSARY	38.00	-
1	REAR TYRE 195/65/15 (SN)	SERVICEABLE	350.00	-
1	SET REAR BUMPER RETAINER CLIP (SN)	NOT NECESSARY	38.00	-
1	SET ROCKER PANEL MOULDING CLIP (SN)	NOT NECESSARY	40.00	-
1	SET TAILLAMP LOWER CLIP (SN)	NOT NECESSARY	30.00	-
1	SET TAILLAMP UPPER CLIP (SN)	NOT NECESSARY	30.00	-
1	REAR BUMPER PROTECTOR (SN)	SERVICEABLE	120.00	-
			1,154.00	68.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.	NOT NECESSARY	380.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR .	NOT NECESSARY	170.00	-
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF PANEL SUB-ASSY,QUARTER ,RH .		6,000.00	200.00
	TO REINSTALL REAR BUMPER PARKING SENSOR .		170.00	50.00
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR .	NOT NECESSARY	380.00	-
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.	NOT NECESSARY	170.00	-
	TO RUST-PROOFING OF THE AFFECTED AREAS.	NOT NECESSARY	170.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
			14,170.00	690.00
	<b>GRAND TOTAL</b>		<b>20,005.27</b>	<b>1,089.95</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>1,089.95</b>

Report Ref No. CC3/FCI20006346/Kda3q2

**KONG SENG CHEONG**

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHD 9418D

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Payo Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

