

8 #
AI
C
3/1
0
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15

Trans-cab Auto Services Pte Ltd
 No. 2 Ang Mo Kio Street 63 Singapore 569111
 Tel No. : 6287 6666 Fax No. : 6257 1330
 CO./GST Reg. No. 201019626G
SHD 9418D

AAD2006-032

Not withank

Measuring B4 paint

81089.95

16 JUN 2020

Vehicle No.: **SHD 9418D**
 Chassis No.: JTDKB3FU303082903
 Vehicle Make: TOYOTA
 Vehicle Model: PRIUS
 Date of Accident : 12.6.2020
 Third Party Insurer : **FCIL**
 Date of Registration : 30/08/2019

PART	LIST		
1 MOULDING ASSY, BODY ROCKER PANEL, RH	\$	594.80	X
1 PANEL SUB-ASSY, QUARTER, RH	\$	871.50	X
1 REAR FENDER LINER	\$	139.80	X
1 DUCT ASSY, QUARTER VENT, RH	\$	67.00	X
1 SEAL, REAR BUMPER SIDE, RH	\$	88.50	X
1 REAR BUMPER	\$	442.60	✓
1 REAR BUMPER UNDER COVER (BLACK)	\$	576.30	X
1 REAR BUMPER SIDE RETAINER RH	\$	117.70	}
1 COVER, FLOOR UNDER, RH	\$	175.10	
1 TAILLAMP LOWER RH	\$	502.00	
1 TAILLAMP UPPER RH	\$	451.80	
1 REAR BUMPER SIDE RH	\$	123.70	
1 REAR WHEEL RIM	\$	1,879.40	}
1 REAR WHEEL RIM COVER	\$	211.50	
TOTAL		\$ 6,241.70	
25%		\$ 1,560.43	
		\$ 4,681.28	

Special Nett

1SET REAR BUMPER CLIP	\$	68.00	✓
2 REAR WINDSCREEN SEALANT	\$	140.00	X
1 WINDSCREEN MOULDING	\$	180.00	X
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	120.00	X
1SET REAR FENDER LINER CLIP	\$	38.00	X
1 REAR TYRE 195/65/15	\$	350.00	X

Trans-cab Auto Services Pte Ltd

AAD2006-032

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9418D

1SET REAR BUMPER RETAINER CLIP	\$	<i>nn</i>	38.00	X
1SET ROCKER PANEL MOULDING CLIP	\$	<i>nn</i>	40.00	X
1SET TAILLAMP LOWER CLIP	\$	<i>nn</i>	30.00	X
1SET TAILLAMP UPPER CLIP	\$	<i>nn</i>	30.00	X
1 REAR BUMPER PROTECTOR	\$	<i>Sn</i>	120.00	X
TOTAL	\$		1,154.00	
TOTAL PARTS	\$		5,835.28	

LABOUR

To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$	<i>nn</i>	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>5</i>	380.00	X
To check steering geometry and computer wheel alignment	\$	<i>5</i>	220.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>5</i>	170.00	X
To transfer of rear windscreen glass to facilitate bodywork repair.	\$	<i>5</i>	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	<i>2001</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>501</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	X

Trans-cab Auto Services Pte Ltd

AAD2006-032

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 9418D

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	440/
To Check Electrical Lighting Concerned.	\$	nn 170.00	X
To Rust-Proofing Of The Affected Areas.	\$	4 170.00	X
To transfer of tire, rim and on wheel balancing.	\$	4 170.00	X
TOTAL	\$	14,170.00	
Over All Total	\$	20,005.28	

(PART-BY-PART) Repair Days

20 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: