

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 37655

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0427/2020/NS
Date : 15-Jun-20

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no : SJZ 6145 X

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

*Hi Adrian,
12 days to repair this vehicle
09/03/2021 - Carrine*

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Ms Loh Chien Nee (Iuo Qianni)
Address : 50 Lorong 40 Geylang
#01-41
Singapore 398074
Telephone : HP +65 92713271
Type of Claim : Own Damage Claim
Policy No. : 2100498620-03
Vehicle No : **SGD 223 U**
Model Code : Audi A4 Sedan 1.4 TFSI S
Model / Year : Jan-17
Engine No : CVN 022715
Chassis No : WAUZZZF44HA063309
Mileage : 79730
Date In : 15-Jun-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Jun-20
Place of Accident : PIE Stevens Road Exit Towards Jurong

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGD 223 U

S/n	Nature of Jobs		Estimated Charges		Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$	360.00	\$	360.00
2	To remove and renew aircond condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$	1,200.00	\$	1,200.00
3	To dismantle and renew front bumper, lhs front fender, bonnet, and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$	5,600.00	\$	3,000.00
4	To respray front bumper, lhs front fender, bonnet and hinges.	\$	3,500.00	\$	1,650.00
SUB TOTAL LABOUR CHARGES		:	\$ 10,660.00	\$	6,210.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGD 223 U

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
		<i>c/t</i>		\$ 8,210.00
5	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	1st accident
6	To dismantle and renew rear bumper. To repair rear lid. Re-organise rear crash management components. Reinstall all parts removed. (Repair rear lid)	\$	1,400.00	\$ 500.00
7	To respray rear bumper and rear lid. (Rear bumper claim 1st accident)	\$	2,000.00	\$ 550.00
8	Supplementary	\$	1,700.00	\$ 800.00
9	To carry out pre-diagnostic check and post-diagnostic check.	S/N \$	384.00	\$ 384.00
TOTAL LABOUR CHARGES		:	\$ 16,504.00	\$ 8,444.00

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/TP/0427/2020/NS
Date 19-Jun-20
Service Advisor Glory Tan
Pages 1 of 1
Regn No SGD 223 U
Model No Audi Sedan 1.4 TFSI S

Quantity	Description	Unit Price	Amount
Labours			
1	To repair rear end panelling.	\$ 700.00	\$ 250.00
2	To respray rear end panelling.	\$ 1,000.00	\$ 550.00
TOTAL		\$ 1,700.00	\$ 800.00

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGD 223 U

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	FRONT BUMPER	\$	2,010.00	\$ 1,608.00
2	FRONT BUMPER FIXING PARTS	\$	269.00	
3	FRONT BUMPER SECURING STRIP	2 \$	67.00	\$ 52.96
4	FRONT BUMPER GRILLE - CENTRE	\$	185.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	\$	198.00	
6	FRONT BUMPER AIR GUIDE - LH	\$	59.00	
7	RADIATOR GRILLE	\$	1,084.00	\$ 867.20
8	FRONT BUMPER AIR GUIDE GRILLE - LH	\$	127.00	
9	FRONT BUMPER CARRIER	\$	757.00	\$ 605.20
10	FRONT BUMPER BRACKET - LH	\$	214.00	\$ 171.20
11	FRONT BUMPER GUIDE SECTION - LH	\$	34.00	
12	FRONT BUMPER GUIDE SECTION - RH	\$	36.00	
13	FRONT BUMPER COVER	\$	120.00	\$ 96.00
14	FRONT BUMPER FOAM FILLER PIECE	\$	117.00	\$ 93.60
15	CAUTION SIGN STICKER	NEC \$	13.00	\$ 10.24
16	AIRCON STICKER	NEC \$	7.00	\$ 5.36
17	LOCK CARRIER BRACKET	\$	129.00	\$ 103.20
18	FRONT BUMPER SUPPORT - LH / RH	2 \$	54.00	\$ 43.36
19	HORN - LH HIGH TONE	\$	119.00	
20	SPRING SHACKLE - LH	\$	27.00	
SUB TOTAL SPARE PARTS CHARGES		:	\$ 5,626.00	\$ 3,656.32

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGD 223 U

S/N	Parts Description	c/f	<u>Damaged Parts & Prices</u>		Remarks
			S/Nett		
				\$	3,656.32
21	BONNET		\$ 2,634.00	\$	2,107.20
22	BONNET ATTACHMENT PARTS		\$ 116.00		
23	BONNET LID HINGE - LH / RH	2	\$ 574.00		
24	BONNET IMPACT PROTECTION - CENTRE		\$ 26.00	\$	20.56
25	BONNET IMPACT PROTECTION - LH / RH	2	\$ 52.00	\$	41.36
26	BONNET STRIKER - LH / RH	2	\$ 94.00		
27	BONNET LID LOCK	2	\$ 403.00		
28	BONNET BOWDEN CABLE - CENTRE		\$ 54.00		
29	BONNET BOWDEN CABLE		\$ 54.00	\$	43.20
30	BONNET RELEASE LEVER		\$ 13.00		
31	FRONT FENDER - LH		\$ 722.00	\$	577.60
32	FRONT FENDER ATTACHMENT PARTS		\$ 190.00		
33	FRONT FENDER CLOSING ELEMENT - LH		\$ 47.00		
34	FRONT FENDER BRACKET - LH		\$ 33.00		
35	DEFORMATION ELEMENT BRACKET - LH		\$ 46.00		
36	FRONT FENDER BRACE - LH		\$ 112.00		
37	WHEEL HOUSING LINER - LH		\$ 226.00		
38	WHEEL HOUSING LINER ATTACHMENT PARTS		\$ 86.00		
39	WHEEL SPOILER		\$ 69.00		
40	WHEEL SPOILER TRIM - LH		\$ 33.00		
SUB TOTAL SPARE PARTS CHARGES :			\$ 5,584.00	\$	6,446.24

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGD 223 U

S/N	Parts Description		<u>Damaged Parts & Prices</u>	
			S/Nett	Remarks
		<i>c/f</i>		\$ 6,446.24
41	STONE CHIP GUARD		\$ 48.00	\$ 37.92
42	FENDER TOP LEDGE COVVER - INNER		\$ 29.00	\$ 23.20
43	FENDER TOP LEDGE COVER - OUTER		\$ 21.00	\$ 16.72
44	LED HEADLIGHT - LH / RH	2	\$ 14,642.00	\$ 11,713.60
45	LIFT CYLINDER - LH		\$ 198.00	
46	LOCK CARRIER		\$ 956.00	
47	COOLANT REGULATOR SUPPORT	2	\$ 71.00	
48	AIRCON CONDENSER		\$ 586.00	\$ 468.80
49	REFRIGERANT LINE PRESSURE SENSOR	2	\$ 368.00	
50	RADIATOR		\$ 615.00	\$ 492.00
51	RADIATOR RUBBER BUSH - LOWER	2	\$ 17.00	
52	RADIATOR RUBBER BUSH - LOWER	2	\$ 24.00	
53	READY MIX COOLANT		\$ 86.00	\$ 68.80
54	ADDITIONAL RADIATOR - LOWER CENTRE		\$ 480.00	
55	TEMPERATURE SENSOR BRACKET		\$ 18.00	\$ 13.68
56	EXTERNAL TEMPERATURE SENSOR		\$ 55.00	
57	RADIATOR FAN RING		\$ 240.00	
58	RADIATOR FAN		\$ 1,877.00	
59	RADIATOR AIR GUIDE - LH / RH	2	\$ 54.00	\$ 22.08
60	RADIATOR AIR GUIDE - LH / RH	2	\$ 24.00	\$ 17.76
SUB TOTAL SPARE PARTS CHARGES :			\$ 20,409.00	\$ 19,320.80

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGD 223 U

S/N	Parts Description		<u>Damaged Parts & Prices</u>		Remarks
			S/Nett		
		<i>c/f</i>			\$ 19,320.80
61	RADIATOR AIR GUIDE - UPPER		\$	15.00	
62	RADIATOR AIR GUIDE - LOWER		\$	21.00	
63	AIR INTAKE AIR DUCT - RH		\$	21.00	
64	AIR INTAKE AIR GUIDE		\$	50.00	
65	AIR INTAKE SEAL		\$	13.00	
66	AIR FILTER		\$	362.00	
67	AIR INTAKE HOSE		\$	90.00	
68	REAR BUMPER		\$	2,079.00	
69	REAR BUMPER FIXING PARTS		\$	69.00	
70	REAR BUMPER SECURING STRIP		\$	210.00	\$ 168.00
71	REAR BUMPER SPOILER		\$	234.00	\$ 187.20
72	REAR LIGHT REFLECTOR - LH / RH	2	\$	78.00	
73	REAR BUMPER CARRIER		\$	845.00	\$ 708.80
74	REAR BUMPER CARRIER SEAL	2	\$	26.00	
75	REAR BUMPER GUIDE SECTION - LH / RH	2	\$	42.00	\$ 17.52
76	REAR PARKING AID SENSOR - INNER / OUTER	2		TBC	
77	REAR PARKING AID SEAL RING	4	\$	14.00	
78	PACKING ADHESIVE		\$	18.00	\$ 14.24
79	AUDI EMBLEM		\$	117.00	\$ 93.20
80	A4 INSCRIPTION		\$	90.00	\$ 71.76
SUB TOTAL SPARE PARTS CHARGES			:	\$ 4,394.00	\$ 20,581.52

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGD 223 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
			\$ 20,581.52
81	TFSI INSCRIPTION	\$ 90.00	\$ 71.76
82	FRONT NO PLATE	S/N \$ 60.00	\$ 60.00
83	REAR NO PLATE	S/N \$ 60.00	
84	SUNDRIES	\$ 400.00	\$ 26.72
TOTAL SPARE PARTS CHARGES		: \$ 36,623.00	\$ 20,740.00
TOTAL LABOUR CHARGES		: \$ 16,504.00	\$ 8,444.00
GRAND TOTAL		: \$ 53,127.00	\$ 29,184.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.