

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 37655

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0427/2020/NS
Date : 15-Jun-20

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle no : **SJZ 6145 X**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Tel: Fax 6338 1504

Owner's Name : Ms Loh Chien Nee (Luo Qianni)
Address : 50 Lorong 40 Geylang
#01-41
Singapore 398074
Telephone : HP +65 92713271
Type of Claim : Own Damage Claim
Policy No. : 2100498620-03
Vehicle No : **SGD 223 U**
Model Code : Audi Sedan 1.4 TFSI S
Model / Year : Jan-17
Engine No : CVN 022715
Chassis No : WAUZZZF44HA063309
Mileage : 79730
Date In : 15-Jun-20
Estimated By : Johnny Boo / Allan Wu
Accident Date : 13-Jun-20
Place of Accident : PIE Stevens Road Exit Towards Jurong

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGD 223 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	S/N \$ 360.00 ✓	
2	To remove and renew aircond condenser, additional radiator, radiator. Check electrical fans and control unit. Pressurise cooling system. To carry out vacuum and regas.	S/N \$ 1,200.00 ✓	
3	To dismantle and renew front bumper, lhs front fender, bonnet, and both headlights. To renew front lock carrier and align to position. Re-organise crash management components. Reinstall all parts removed.	\$ 5,600.00 1750	(Without Lock Carrier)
4	To respray front bumper, lhs front fender, bonnet and hinges. x	\$ 3,500.00 1650	3000 (with Lock carrier)
SUB TOTAL LABOUR CHARGES		: \$ 10,660.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SGD 223 U

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
5	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	X
6	To dismantle and renew rear bumper. To repair rear lid. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,400.00	500
7	To respray rear bumper and rear lid.	\$ 2,000.00	1400 550
8	To carry out pre-diagnostic check and post-diagnostic check.	S/N \$ 384.00	✓ 190
TOTAL LABOUR CHARGES		: <u>\$ 14,804.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGD 223 U

S/N	Parts Description		Damaged Parts S/Nett	& Prices Remarks
1	FRONT BUMPER <i>Delvnd</i>	\$	2,010.00	✓ 1608
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$	269.00	x
3	FRONT BUMPER SECURING STRIP new <i>new</i>	2 \$	67.00	✓ 50.96
4	FRONT BUMPER GRILLE - CENTRE <i>new</i>	\$	185.00	x
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE <i>new</i>	\$	198.00	x
6	FRONT BUMPER AIR GUIDE - LH <i>new</i>	\$	59.00	x
7	RADIATOR GRILLE <i>crushed</i>	\$	1,084.00	✓ 867.20
8	FRONT BUMPER AIR GUIDE GRILLE - LH <i>new</i>	\$	127.00	x
9	FRONT BUMPER CARRIER <i>Best</i>	\$	757.00	✓ 605.20
10	FRONT BUMPER BRACKET - LH <i>Delvnd</i>	\$	214.00	✓ 171.20
11	FRONT BUMPER GUIDE SECTION - LH	\$	34.00	+
12	FRONT BUMPER GUIDE SECTION - RH	\$	36.00	+
13	FRONT BUMPER COVER <i>Delvnd</i>	\$	120.00	✓ 96.00
14	FRONT BUMPER FOAM FILLER PIECE <i>Delvnd</i>	\$	117.00	✓ 93.60
15	CAUTION SIGN STICKER <i>3 per</i>	NEC \$	13.00	✓ 10.24
16	AIRCON STICKER	NEC \$	7.00	✓ 5.36
17	LOCK CARRIER BRACKET <i>crushed</i>	\$	129.00	✓ 103.20
18	FRONT BUMPER SUPPORT - LH / RH <i>Delvnd</i>	2 \$	54.00	✓ 43.36
19	HORN - LH HIGH TONE	\$	119.00	x
20	SPRING SHACKLE - LH <i>new</i>	\$	27.00	+
SUB TOTAL SPARE PARTS CHARGES			: \$ 5,626.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No.SGD 223 U

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remarks
21	BONNET <i>Dented</i>	\$ 2,634.00	✓ 2107.20
22	BONNET ATTACHMENT PARTS <i>Not nec</i>	\$ 116.00	X
23	BONNET LID HINGE - LH / RH <i>Not nec</i>	2 \$ 574.00	+
24	BONNET IMPACT PROTECTION - CENTRE <i>2 per</i>	\$ 26.00	✓ 20.56
25	BONNET IMPACT PROTECTION - LH / RH	2 \$ 52.00	✓ 41.36
26	BONNET STRIKER - LH / RH <i>Not nec</i>	2 \$ 94.00	X
27	BONNET LID LOCK <i>Not nec</i>	2 \$ 403.00	+
28	BONNET BOWDEN CABLE - CENTRE <i>Not nec</i>	\$ 54.00	+
29	BONNET BOWDEN CABLE <i>2 nec</i>	\$ 54.00	✓ 43.20
30	BONNET RELEASE LEVER <i>Not nec</i>	\$ 13.00	+
31	FRONT FENDER - LH <i>Buckled</i>	\$ 722.00	✓ 577.60
32	FRONT FENDER ATTACHMENT PARTS <i>Not nec</i>	\$ 190.00	X
33	FRONT FENDER CLOSING ELEMENT - LH <i>Not nec</i>	\$ 47.00	+
34	FRONT FENDER BRACKET - LH <i>Not nec</i>	\$ 33.00	+
35	DEFORMATION ELEMENT BRACKET - LH <i>Not nec</i>	\$ 46.00	X
36	FRONT FENDER BRACE - LH <i>Not nec</i>	\$ 112.00	X
37	WHEEL HOUSING LINER - LH <i>Not nec</i>	\$ 226.00	+
38	WHEEL HOUSING LINER ATTACHMENT PARTS <i>Not nec</i>	\$ 86.00	X
39	WHEEL SPOILER <i>Not nec</i>	\$ 69.00	+
40	WHEEL SPOILER TRIM - LH <i>Not nec</i>	\$ 33.00	+
SUB TOTAL SPARE PARTS CHARGES		: \$ 5,584.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGD 223 U

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
41	STONE CHIP GUARD <i>New</i>	\$ 48.00	✓	37.92
42	FENDER TOP LEDGE COVVER - INNER <i>2 Dec. Allen</i>	\$ 29.00	✓	23.20
43	FENDER TOP LEDGE COVER - OUTER	\$ 21.00	✓	16.72
44	LED HEADLIGHT - LH / RH <i>LH cracked</i>	2 \$ 14,642.00	7321	11,713.60
45	LIFT CYLINDER - LH <i>New</i>	\$ 198.00	+	
46	LOCK CARRIER <i>New</i>	\$ 956.00	X	
47	COOLANT REGULATOR SUPPORT <i>New</i>	2 \$ 71.00	X	
48	AIRCON CONDENSER <i>Dented</i>	\$ 586.00	✓	468.80
49	REFRIGERANT LINE PRESSURE SENSOR <i>New</i>	2 \$ 368.00	+	
50	RADIATOR <i>Dented</i>	\$ 615.00	3	492.00
51	RADIATOR RUBBER BUSH - LOWER <i>New</i>	2 \$ 17.00	X	
52	RADIATOR RUBBER BUSH - LOWER <i>New</i>	2 \$ 24.00	X	
53	READY MIX COOLANT <i>New</i>	\$ 86.00	✓	68.80
54	ADDITIONAL RADIATOR - LOWER CENTRE <i>New</i>	\$ 480.00	+	
55	TEMPERATURE SENSOR BRACKET <i>New</i>	\$ 18.00	✓	13.68
56	EXTERNAL TEMPERATURE SENSOR <i>New</i>	\$ 55.00	X	
57	RADIATOR FAN RING <i>New</i>	\$ 240.00	X	
58	RADIATOR FAN <i>New</i>	\$ 1,877.00	X	
59	RADIATOR AIR GUIDE - LH / RH <i>LH cracked</i>	2 \$ 54.00	27	22.08
60	RADIATOR AIR GUIDE - LH / RH <i>RH cracked</i>	2 \$ 24.00	✓	17.76
SUB TOTAL SPARE PARTS CHARGES		: <u>\$ 20,409.00</u>		

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGD 223 U

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
61	RADIATOR AIR GUIDE - UPPER <i>new</i>	\$	15.00	+
62	RADIATOR AIR GUIDE - LOWER <i>new</i>	\$	21.00	+
63	AIR INTAKE AIR DUCT - RH <i>new</i>	\$	21.00	+
64	AIR INTAKE AIR GUIDE <i>2</i>	\$	50.00	+
65	AIR INTAKE SEAL <i>new</i>	\$	13.00	+
66	AIR FILTER	\$	362.00	+
67	AIR INTAKE HOSE	\$	90.00	+
68	REAR BUMPER <i>Del d new</i>	\$	2,079.00	+ X
69	REAR BUMPER FIXING PARTS <i>new</i>	\$	69.00	+
70	REAR BUMPER SECURING STRIP <i>new</i>	\$	210.00	✓ 168.00
71	REAR BUMPER SPOILER <i>Del d</i>	\$	234.00	✓ 187.20
72	REAR LIGHT REFLECTOR - LH / RH <i>new</i>	2 \$	78.00	+
73	REAR BUMPER CARRIER <i>Best</i>	\$	845.00	3 ✓ 708.80
74	REAR BUMPER CARRIER SEAL <i>new</i>	2 \$	26.00	X
✓ 75	REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>	2 \$	42.00	✓ 17.52
76	REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	TBC	+
77	REAR PARKING AID SEAL RING <i>new</i>	4 \$	14.00	+ X
78	PACKING ADHESIVE <i>2</i>	\$	18.00	✓ 14.24
79	AUDI EMBLEM <i>new</i>	\$	117.00	✓ 93.20
80	A4 INSCRIPTION	\$	90.00	✓ 71.76
SUB TOTAL SPARE PARTS CHARGES		:	<u><u>\$ 4,394.00</u></u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGD 223 U

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
81	TFSI INSCRIPTION <i>New</i>	\$	90.00	✓ 71.76
82	FRONT NO PLATE <i>Deleted</i>	S/N \$	60.00	✓ 60.00
83	REAR NO PLATE <i>New</i>	S/N \$	60.00	X.
84	SUNDRIES <i>New</i>	\$	400.00	✓ 26.72
TOTAL SPARE PARTS CHARGES		:	\$ 36,623.00	
TOTAL LABOUR CHARGES		:	\$ 14,804.00	
GRAND TOTAL		:	\$ 51,427.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lj
Surveyed Date : 16/06/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 09 Days (Without lock corner)
12 Days (With lock corner).

Please Note

: This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 - Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0427/2020/NS 19-Jun-20 Glory Tan 1 of 1 SGD 223 U Audi Sedan 1.4 TFSI S
Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	To repair rear end panelling.	\$ 700.00	250
2	To respray rear end panelling.	\$ 1,000.00	550
TOTAL		\$ 1,700.00	

For Premium Automobiles Pte Ltd

Adrian Ling
19/06/20

Authorised Signature

Add 1 day
H.S.