

## REPAIR ESTIMATE\*

**DATE: 17. Jun. 2020**

DOA: 16. Jun. 2020

**AIG**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	Front Bumper Cover			\$1,052.20
1	Front Bumper Side Bracket – LH			\$24.60
1	Front Bumper Top Bracket – LH			\$22.40
10	Front Bunmper Clips		\$2.20	\$22.00
1	Front Bumper Grille – LH			\$93.60
1	Headlamp Support Panel			\$907.40
1	Front Fender – LH			\$663.00
1	Front Fender Shield – LH			\$174.90
1	Headlamp – LH			\$1,388.00
	SUB TOTAL			\$4,348.10
	LESS 20%			\$869.62
	DISCOUNTED TOTAL			\$3,478.48
1	Advertisement – LHF Fender			\$100.00
				\$100.00
	Labour Charge			
1	Panel Beating			\$600.00
1	Spray Painting Charge			\$500.00
1	Tuff Kote			\$80.00
1	Wiring Charge			\$80.00
	TOTAL LABOUR			\$1,260.00
	ESTIMATE TOTAL			\$4,838.48
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				