

YEE KEONG MOTOR ENGINEERING

No. 14 Penjuru Road Singapore 609125 Tel/Fax: 62620218 Hp:97808928

FIRST CAPITAL INSURANCE LTD

POLICY NO.D-20094877MFC/1

Date 16/6/20

VEHICLE NUMBER : GBG 2683 E / YANG KEE LOGISTICS PTE LTD / FIAT DOBLO CARGO

Date of Accident 13/06/2020. - Quotation for Own Damage Claim

PARTS SUPPLY

1	1pc	Rear bumper <i>de</i> ✓	556.32
2	1pc	Rear bumper tow hook cover o/s <i>X SVC</i>	84.00 X
3	1pc	Rear bumper reinforcement <i>bt</i> ✓	414.40
4	6pcs	Rear bumper reinforcement nuts @\$5 <i>ne</i> ✓	30.00
5	29pcs	Rear bumper clips @\$4 <i>ne</i> ✓	116.00
6	1pc	Rear bumper side retainer o/s <i>ne</i> ✓	183.25
7	1pc	Rear o/s wheel rim cap <i>de</i> ✓	258.20
8	1pc	Front o/s fender <i>bu</i> ✓	253.08
9	1pc	O/s Headlamp <i>bro</i> ✓	763.80
10	1pc	Front bumper lower spoiler <i>scr</i> ✓	608.96
11	1pc	Front bumper <i>de</i> ✓	796.48
12	1pc	Front o/s fender liner <i>cr</i> ✓	188.25
13	20pcs	Front bumper clips @\$4 <i>ne</i> ✓	80.00
14	6pcs	Front bumper retainer o/s <i>cr</i> ✓	82.50
15	1pc	Front o/s fender top garnish <i>cr</i> ✓	288.25

4619.49

10%

4157.54

Remove the necessary affected parts,
cut/weld front o/s Fender, straighten front o/s wheel
house, rear o/s fender, o/s headlamp panel
and replace parts

Reset wheel alignment - 4 wheel alignment

Remove and refit o/s headlamp and
refocus o/s headlamp beam

Putty and Spraypaint

Tuff Kote

Reset complete electrical using diagnostic tools

<i>Gasul</i>	880.00	<i>700</i>
<i>4p 90010068</i>	150.00	<i>80</i>
<i>7 days</i>	50.00	<i>30</i>
<i>4s</i>		
<i>17/06/2020</i>	1400.00	<i>800</i>
<i>@ 12430</i>		
<i>EXCESS: TBA</i>	100.00	<i>40</i>
<i>Resurvey after repair</i>	150.00	<i>60</i>
TOTAL	7433.49	

1710

4157.54

1710.00

5867.54

20%

4694.03

4s - 4,700

7 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____