



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBG 2683E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	556.32	556.32
1	REAR BUMPER TOW HOOK COVER O/S	SERVICEABLE	84.00	-
1	REAR BUMPER REINFORCEMENT	BENT	414.40	414.40
6	REAR BUMPER REINFORCEMENT NUTS @ \$5.00	NECESSARY	30.00	30.00
29	REAR BUMPER CLPS @ \$4.00	NECESSARY	116.00	116.00
1	REAR BUMPER SIDE RETAINER O/S	NECESSARY	183.25	183.25
1	REAR O/S WHEEL RIM CAP	DEFORMED	258.20	258.20
1	FRONT O/S FENDER	BUCKLED	253.08	253.08
1	O/S HEADLAMP	BROKEN	763.80	763.80
1	FRONT BUMPER LOWER SPOILER	SCRATCHED	608.96	608.96
1	FRONT BUMPER	DEFORMED	796.48	796.48
1	FRONT O/S FENDER LINER	CRACKED	188.25	188.25
20	FRONT BUMPER CLIPS @ \$4.00	NECESSARY	80.00	80.00
6	FRONT BUMPER RETAINER O/S	CRACKED	82.50	82.50
1	FRONT O/S FENDER TOP GARNISH	CRACKED	288.25	288.25
	LESS 10% DISCOUNT		-	-461.95
			4,703.49	4,157.54
	<u>LABOUR</u>			
	REMOVE THE NECESSARY AFFECTED PARTS, CUT / WELD FRONT O/S FENDER, STRAIGHTEN FRONT O/S WHEEL HOUSE, REAR O/S FENDER, O/S HEADLAMP PANEL AND REPLACE PARTS.		880.00	700.00
	RESET WHEEL ALIGNMENT - 4 WHEEL ALIGNMENT.		150.00	80.00
	REMOVE AND REFIT O/S HEADLAMP AND REFOCUS O/S HEADLAMP BEAM.		50.00	30.00
	PUTTY AND SPRAY PAINT.		1,400.00	800.00
	TUFF KOTE.		100.00	40.00
	RESET COMPLETE ELECTRICAL USING DIAGNOSTIC TOOLS.		150.00	60.00
			2,730.00	1,710.00
	GRAND TOTAL		7,433.49	5,867.54



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,700.00
LESS EXCESS			-750.00
NETT LIABILITY			3,950.00

Report Ref No. CS4/FCI20006356/R1sf3s2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.