

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To:	China Taiping Insurance (Singapore) Pte. Ltd. 3 Anson Road #16-00 Springleaf Tower Singapore 079909	From:	LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn:	Elaine Cheong	Date:	18 Jun 2020

**Preliminary Advice**

Insured Vehicle No	: GR158B	Accident Date	: 21/11/2018
TP Vehicle No	: SKV2632S	Assignment Date	: 22/11/2018
Make	: TOYOTA COROLLA ALTIS	Est. Duration of Repair	: 3.00
Date of Inspection	: 17/06/2020		
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,930.95
Revised Amount	:S\$	2,793.10
Check Items (Estimated)	:S\$	777.85
Total	:S\$	3,570.95
Lump Sum Repair		:S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- (   ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (   ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (   ) Other comments :