

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle Number : SKZ 176J

Vehicle Model : HONDA VEZEL HYBRID

Accident Date : 10.06.2020

Original Reg Date : 05.01.2016

Date : 16.06.2020

Chassis : RU31115657

TP Ins. **FIRST CAPITAL**

ESTIMATE

1	1 pc	Tailgate			1,265.00	x R
2	1 pc	Tailgate Badge			58.00	nei X nn
3	1 pc	Tailgate Emblem VEZEL			65.00	nei X ✓
4	1 pc	Tailgate Emblem Hybrid			68.00	nei X ✓
5	1 pc	Tailgate Weatherstrip			190.00	de ✓
6	1 pc	Rear Bumper			980.00	de ✓ 777.90
7	2 pcs	Rear Bumper Side Retainers	42.00	LH X nn	84.00	RH de ✓ 42
8	2 pcs	Rear Bumper Attachment Retainers	39.00	LH X nn	78.00	RH de ✓ 39
9	1 set	Rear Bumper Clips		30	50.00	nei ✓
10	1 pc	Rear Bumper Side Pad RH			275.00	de ✓
11	1 pc	Rear Bumper Under Cover			196.00	x nn
12	1 set	Rear Bumper Under Cover Clips			30.00	x nn
13	1 pc	End Panel			652.00	de ✓ 515.60
14	1 pc	End Panel Top Trim			176.00	de ✓
15	1 set	End Panel Top Trim Clips		10	30.00	nei ✓
16	1 pc	Spare Tyre Panel Top Board			462.00	x nn
17	1 pc	Spare Tyre Panel Top Tray			381.00	de ✓
18	1 pc	Alarm Sensor Speaker			150.00	x nn
19	1 pc	Taillamps RH			nn x 680.00	
20	1 pc	Taillamps Inner Sealer			nn x 38.00	
21	1 set	Taillamps Clip			nn x 25.00	
22	1 pc	Rear Fender Inner Trim RH			nn ✓ 335.00	
23	1 set	Rear Fender Inner Trim Clips			nn ✓ 30.00	
24	1 pc	Rear Fender Arch Garnish RH			de ✓ 195.00	
25	1 set	Rear Fender Arch Garnish Clip			10 nei ✓ 30.00	
					6,523.00	3139.50
					Less 20%	1,304.60
						5,218.40
						2511.60

EM-1 AUTO PTE LTD

BLK 8 SIN MING INDUSTRIAL ESTATE SECTOR C

#01-68 SINGAPORE 575643

Contact Number: 6452 3298 (O) 9666 6556 (H/P) 6457 5776 (F)

Email Address: em1autopteltd@gmail.com

COMPANY / GST REG. NO. : 201316380R

Vehicle No : SKZ 176J

B/F

5,218.40

Special Nett

1	1 set	Reverse Sensor		200	250.00
2	1 set	Body Panel Joint Sealant		40	120.00

nw ✓
nw ✓
240

Labour charge

Panel Beating		1,000.00
Spray painting - 2 Tone Pearl		1,000.00
Check Wiring		30.00
Anti rust		80.00
Remove and install carpet and seat.		100.00
Remove and install reverse sensor		90.00

600.
800
✓
30.
50.
30

7,888.40

Less 20% 1,577.68

Lump sum 6,310.72

1540

Tanfan 97495749
WP
Lump sum
Repair after repair
6 days
tanfan @ lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display **damaged** part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2'511.60

240

1540

4291.60

4543400, 6 days

*