

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 7930P -

ROEL

*Not Authorized
 11 Sep @ 1900p*

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 7930P -
 KL1LA69RJBB126546
 CHEVROLET
 CHEVROLET EPICA 2.0
 04.02.15
 AXA

PART			LIST
1	1	Front Bumper	\$ R 1,202.00 X
2	1	Front Bumper Retainer LH	\$ S 102.00 X
1	1	Resonator (B/S Fender LH) AIR BOX	\$ S 134.67 X
2	1	Resonator Hose	\$ R 37.00 X
3	1	Front Headlamp LH	\$ C 816.00 ✓
4	1	Front Fender LH	\$ B 837.60 ✓
5	1	Front Fender Liner LH	\$ D 47.00 ✓
6	1	Front Door LH	\$ R 1,133.00 X
7	1	Front Side View Mirror LH	\$ S 939.00 X
8	1	Side Rocker Panel Garnish LH	\$ R 236.40 X
TOTAL		\$	5,484.67
10%		\$	548.47
		\$	4,936.20

Special Nett

1 Set	Front Bumper Fastener Clip	\$	nn 30.00 X
1 Set	Front Fender Liner Clip LH	\$	nn 30.00 ✓
1	Door Sticker "Trans-cab" LH	\$	nn 80.00 X
1set	Side Rocker Panel Garnish Clip LH	\$	nn 60.00 X
1	Front Tyre LH	\$	S 360.00 X
1	Front Wheel Rim LH	\$	S 254.00 X
1	Hub Cup Rim Front	\$	S 35.00 X
TOTAL		\$	849.00

TOTAL PARTS \$ 5,785.20

Panel Beating, Knocking And Straightening The
 Necessary Portion, Remove And Renewal Of
 Parts, Adjust And Realign The Same

\$

2,800.00

3001

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHB 7930P -

ROEL

To Rust-Proofing Of The Affected Areas.	\$	220.00 <i>300</i>
Putty and Spray Painting Of The Affected	\$	2,700.00 <i>400</i>
To Check Electrical Lighting Concerned.	\$	170.00 <i>200</i>
To check steering geometry and computer wheel alignment	\$	220.00 <i>600</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nr</i> 170.00 <i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nr</i> 170.00 <i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nr</i> 170.00 <i>X</i>
TOTAL		\$ 6,620.00
Over All Total		\$ 12,405.20

REPAIR DAYS

10 DAYS

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: