6/17/2021 Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CC4/III20006374/KEA3Q2

Date:

No

17/06/2021

REFERENCE

Date of Loss:

Reg. Date:

Handling Insurer: India International Insurance Pte Ltd Policy No:

MCOM0015 SHA1672D

Engine No:

Chassis No:

Odometer:

Footbrake (Serviceable):

Pre-accident Condition:

Claimant Vehicle No: SLJ6935T

12/06/2020

Insured Vehicle No:

Nature of Claim:

ΤP

Claim No:

MCT20060125

16031117263306PS

103219 km

SADCA2AV1HA051033

Yes

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLJ6935T**

Make & Model: JAGUAR F-PACE PRESTIGE, 3.0 V6 SC SR (A)

21/12/2016 (Man. Year: 2016)

Yes

Colour: Metallic Grey

Engine Capacity: 2995 cc

Market Value/New Car Price: N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable): Yes

Engine Modification:

Handbrake (Serviceable):

CONDITION OF TYRES

Front Tyre Size: Rear Tyre Size: 255/55 R20 255/55 R20

Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm Front Right Side: Rear Right Side: Continental 8 mm Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		0.00	0.00	0.00	-
Miscellaneous Items		0.00	0.00	0.00	
Labour		800.00	690.00	110.00	13.75
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Gross Total (S\$)	800.00	690.00	110.00	13.75
	+ GST 7.00/7.00% (S\$)	56.00	48.30	7.70	13.75

117.70 13	738.30	856.00	Nett Amount (S\$)
	360.00	+ Loss of Use (3.0 x S\$120.00/day) (S\$)	
	7.45	+ Doc/Search Fee (S\$)	4
	1,105.75	Nett Liability (S\$)	
	1.100.00	Il Sum Settlement (S\$)	Globa

INSPECTION

Date of Assignment: 17/06/2020

K Kim Hin Auto Pte Ltd (HQ) Date Inspected: 17/06/2020 Inspected At:

160 Sin Ming Drive #02-20, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other circumstances is hereby expressly

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Aug 2020)

JAGUAR F-PACE PRESTIGE 3.0 V6 SC SR (A) (Model not available in database) Parts: N/A

Repairer's (Price-denominated Standard List) Labour:

(Unsubmitted, no print-code for SLJ6935T) **Print Code:**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Adjuster Report

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No Particulars	Lab.Type	Repairer's	Amount
Labour Items			
1 TO REMOVE, CUT OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW AFFECTED PARTS		300.00	250.00
2 TO PUTTY AND RESPRAY ON AFFECTED PORTIONS	New	500.00	440.00
Gross Labour Cost (S\$)		800.00	690.00
Report was unsubmitted during this print-out.			

< END OF ESTIMATES >