

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20006387/R1YF3E2

Date: 27/07/2020

REFERENCE

| | | | |
|------------------------------|---|-----------------------------|-------------------------|
| Handling Insurer: | China Taiping Insurance (Singapore) Pte. Ltd. | Policy No: | DMCVSNA00038382000 |
| Claimant Vehicle No : | SCM7164K | Insured Vehicle No : | YM36H |
| Date of Loss: | 10/06/2020 | Nature of Claim: | TP |
| | | Claim No: | SNM20D202130/C02/CHNGPW |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No: | SCM7164K | Engine No: | 19415109B48B20A |
| Make & Model: | BMW 520i, 2.0 (A) | Chassis No: | WBAJA12060BJ18849 |
| Reg. Date: | 31/01/2018 (Man. Year: 2017) | Odometer: | 37847 km |
| Colour: | Grey | | |
| Engine Capacity: | 1998 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition: | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: |

CONDITION OF TYRES

| | | | |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size: | 245/45 R18 | Rear Tyre Size: | 245/45 R18 |
| Front Left Side: | Pirelli 6 mm | Rear Left Side: | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts | 40.00 | 40.00 | 0.00 | 0.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,490.00 | 1,934.00 | 556.00 | 22.33 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Gross Total (S\$) | 2,530.00 | 1,974.00 | 556.00 | 21.98 |
| + GST 7.00/7.00% (S\$) | 177.10 | 138.18 | 38.92 | 21.98 |
| Nett Amount (S\$) | 2,707.10 | 2,112.18 | 594.92 | 21.98 |

INSPECTION

| | | |
|-----------------------------|--------------------------|--|
| Date of Assignment: | 17/06/2020 | |
| Date Inspected: | 06/07/2020 Inspected At: | Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941 |
| Estimated Period of Repair: | 3.0 days | |

Adjuster: MOHD RASUL

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 27 Jul 2020) |
| Parts: | 143 | BMW 520I 2.0 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SCM7164K) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|--------------------------|-----|----------|-------------|-----------|--------------|------------------------------|
| 1 | 1 | | *SUNDRIES | Necessary | 40.00 FS | *40.00 FS |
| | | | | | | F=Franchise part. S=SpcNett. |
| Total Parts (S\$) | | | | | 40.00 | 40.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TO REPAIR REAR RIGHT FENDER | New | 1,275.00 | 850.00 |
| 2 | PAINTING REAR RIGHT FENDER | New | 1,038.00 | 934.00 |
| 3 | TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION | New | 177.00 | 150.00 |
| Gross Labour Cost (S\$) | | | 2,490.00 | 1,934.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >