



Final Report

Estimate No. : **b1 55263**
Date Estimated : **16/06/2020**
Prepared By : **Inthiran A/L Thurasamy**

- ESTIMATE REPAIR FOR -
Lim Thiam Lee
26 Toh Yi Road

- ACCOUNT - 135
China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

Singapore 596506

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SCM7164K	WBAJA12060BJ188	31/01/2018	520iA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To make good the rear right fender including knock out dented area caused by the accident.	850.00		850.00
To respray rear right fender.	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
Sundries.	40.00		40.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	0.00
Total Labour & Parts :	1,974.00
Deduction for Excess :	0.00
Total Repair Costs less Excess:	1,974.00
GST @7%:	138.18
Grand Total :	2,112.18

Loss Of Use = \$120 x 3

GIA SEARCH FEE = \$2