## **Performance Motors Limited**

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## **Final Report**

Estimate No. :

b1 55263

Date Estimated:

16/06/2020

Prepared By :

Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

- ACCOUNT -135

**Lim Thiam Lee** 26 Toh Yi Road China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Singapore 596506

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

**SCM7164K** 

WBAJA12060BJ188 31/01/2018

520iA

0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
Made Good rear right fender and knocking at accident area include remove attachment parts to facilitates repairs.	850.00	0.00	850.00
To respray rear right fender.	934.00	0.00	934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00	0.00	150.00
Sundries.	40.00	0.00	40.00

# SUPPLEMENTARY ITEMS

Total Labour:

1,974.00

Total Parts:

Total Labour & Parts:

1,974.00

Deduction for Excess:

Total Repair Costs less Excess:

GST @7%:

1,974.00 138.18

Grand Total:

2,112.18

Loss Of Use=@120 x 1

GIA SEARCH FEE=\$2

## **Performance Motors Limited**

A member of the Sime Darby Group Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## **Final Report**

Estimate No. :

b1 55263

Date Estimated:

16/06/2020

Prepared By :

Inthiran A/L Thurasamy

- ESTIMATE REPAIR FOR -

- ACCOUNT -135

**Lim Thiam Lee** 26 Toh Yi Road China Taiping Insurance (S) Pte Ltd

3 Anson Road

#16-00 Springleaf Tower

Singapore 079909

Singapore 596506

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SCM7164K

WBAJA12060BJ188 31/01/2018

520iA

0

DESCRIPTION	ORIGINA	L PRICE	DISC. %	NETT
To make good the rear right fender including knock out dented area caused by the accident.		850.00		850.00
To respray rear right fender.		934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.		150.00		150.00
Sundries.		40.00		40.00
DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT

# SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts:	0.00
Total Labour & Parts:	1,974.00
Deduction for Excess:	0.00
Total Repair Costs less Excess:	1,974.00
GST @7%:	138.18
Grand Total :	2,112.18

Loss Of Use = \$120x1

GIA SEARCH FEE = \$2