



Xin Yun Auto Private Limited
辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

FBL732J VESPA GTS SUPER 300IE ABS/ASR

No	Qty	Parts Description	Estimated Parts Price
1	2	Front fork tubes assy whole set / BT	\$ 685 - /
2	1	Front mugcard / CUT	\$ 395.00 /
3	1	Fork under bracket X NM	\$ 185.00 X
4	1	Front rim shaft X NM	\$ 285.00 X
5	1	Front brake disc X NM	\$ - X
6	1	Front fender X NM	\$ 125.00 X
7	1	Front fender seal X NM	\$ 105.00 /
8	1	Handle bar / BT	\$ 225.00 /
9	1	Hand grip 1 set X NM	\$ 125.00 X
10	1	Handle bar inner bracket X NM	\$ 125.00 X
11	1	Side mirror left X NM	\$ - X
10	1	Side mirror right X NM	\$ - X
11	1	Front signals (LH) / CUT	\$ 135.00 /
12	1	Front signal panel cover X (C/w frame) Repair / BT	\$ 225.00 X
13	1	Front signal lower garnish X NM	\$ 105.00 X
14	1	Headlamp X NM	\$ - X
15	1	Fairing assy 1 set X NM	\$ - X
16	1	Side cowling inner garnish X NM	\$ 95.00 X
17	1	Centre inner panel X NM	\$ 155.00 X
18	1	Front footrest bracket X NM	\$ 285.00 X
19	1	Front n/s footrest rubber X NM	\$ 95.00 X
20	1	Brake pedal X NM	\$ 55.00 X
21	1	Rear n/s footrest / CUT	\$ 125.00 /
22	1	Rear n/s footrest bracket X NM	\$ 85.00 X
23	1	Rear taillamp X NM	\$ 135.00 X
24	2	Rear fender X (C/w frame) Repair / BT	\$ 225.00 X
25	1	Engine cover metal X (C/w frame) Repair / BT	\$ 380.00 X
26	1	Swing arm X NM	\$ - X
27	1	Absorber 1 set X NM	\$ 480.00 X
28	1	LH Side Garnish Cracked (LH front Body mouldings) / CUT	\$ 165.00 /
29	1	Fuel tank cover x1 set metal X (C/w frame) X Repair / BT	\$ 680.00 X
30	1	Rear midshield cover (refer to engine cover) / CUT (LH)	\$ 385.00 /
30	1	Clutch lever X NM	\$ 220.00 X
31	1	Balancer / CUT (LH)	\$ 125.00 /
32	1	Exq cover X NM	\$ 245.00 X
33	1	H/P brake broken X NM	\$ 285.00 X

Sub-total parts

\$ 6,090.00

Less 10%

\$ 609.00

\$ 5,481.00

2249
-10%
2016



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

FBL732J VESPA GTS SUPER 300IE ABS/ASR

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	1	Number plate front and behind 1 set / N/C	\$ 50.00 30 /
2	1	Steering cone 1 set / N/C	\$ 90.00 /
3	1	Engine cover and light stricker / N/C	\$ 95.00 /
Sub-total Special Nett Items			\$ 235.00
Total parts			\$ 5,716.00 215



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunautol@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

FBL732J VESPA GTS SUPER 300IE ABS/ASR

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts, workmanship to dismantle above damaged parts, re-align body structure and damaged consistent to the accident	\$ 700.00 500
2	To putty and spray painting front portion.	\$ 800.00 400
3	To apply anti rust proofing to front left affected area	\$ 120.00 30
4	To check electrical system, wiring and focus front headlamp.	\$ 80.00 30
5	To remove and install front padel, brake padel and absorber	\$ 150.00 50
6	To balance the wheel.	\$ 50.00 X
7	To conduct alignment.	\$ 50.00 30
Total labour :		\$ 1,950.00

Total parts : \$ 8,846.20
Total labour : \$ 1,950.00
Total repair cost : \$ 10,796.20

1040

Steve (LKK)

WHL Mill

L/S

Ry AL sy

23/6/20, 3.00pm

5 days

P-2016

M-215

L-1040

3271

Supp-2121

5392

L/S-4313.60
= 4300

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

FBL732J VESPA GTS SUPER 300IE ABS/ASR

(Supplementary)

No	Qty	Parts Description	Estimated Parts Price
1	1	Radiator assy / <i>131</i>	\$ 485.00 ✓
2	1	Fan motor assy / <i>Front cover</i> / <i>BR</i>	\$ 125 / 385.00
3	1	Radiator hose X <i>NMI</i>	\$ 95.00 X
4	1	Coolant / <i>MC</i>	\$ 35.00 20 ✓
5	1	Side panel left side / <i>BR</i>	\$ 225.00 ✓
6	1	Side panel right side / <i>CUT</i>	\$ 225.00 ✓
7	1	Side panel sticker 1 set for both / <i>NA</i>	\$ 80.00 ✓
8	1	Side spoiler X <i>NMI</i>	\$ 68.00 ✓
9	1	Air-intake cover / <i>BR (Engine cover LH)</i>	\$ 185.00 ✓
10	1 <i>glue</i>	viov board / <i>CRU</i>	\$ 395.00 ✓
11	1 <i>glue</i>	viov board cover / <i>CRU</i>	\$ 195.00 ✓
12	1	Step board X <i>NMI</i>	\$ 285.00 X
13	1	Step board seals 1 set X <i>NMI</i>	\$ 2290 225.00 X
14	1	Limited editional verio-cover / <i>CUT</i>	\$ -10% 355.00 ✓
14	1	Labour to replace radiator and fan motor assy and top up coolant	\$ 2061 ✓ 120.00 30
15	1	Labour to replace side panel, air-intake and viov board and cover	\$ 120.00 30
Sub-total parts			\$ 3,478.00
Less 10%			\$ 347.80
Supplementary Parts Total			\$ 3,130.20

2121

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Steve 1/7/20