

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 321H**AAD2006-036***Not Authorized
11 Sep 8 3600h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

16 JUN 2020**SHD 321H**

VF1ABL15AUC282427

RENAULT

LATITUDE

15.6.2020

FCIL

4/3/2016

	PART
1	BUMPER COVER REAR
1	BUMPER LOWER REAR
1	BUMPER BRACKET CTR REAR
1	BUMPER BRACKET SIDE RH REAR
1	BUMPER RETAINER RH REAR
1	BUMPER REFLECTOR RH
1	BUMPER BRACKET SIDE LH REAR
1	BUMPER RETAINER LH REAR
1	BUMPER REFLECTOR LH
1	BUMPER BEAM REAR
1	BUMPER BEAM BRACKET LH REAR
1	BUMPER BEAM BRACKET RH REAR
1	BUMPER BLOCK RH REAR
1	BOOT REAR
1	BOOT FINISHER
1	BOOT WHEATERSTRIP
1	BOOT REFLECTOR LAMP LH
1	BOOT REFLECTOR LAMP RH
1	BOOT BADGE 'RENAULT'
1	BOOT BADGE
1	BOOT STRUT LH
1	BOOT STRUT RH
1	BOOT HINGE LH
1	BOOT HINGE RH
1	BOOT TRIM BOARD
1	BOOT LOCK

	LIST
\$	Bu 561.70 ✓
\$	Ad/br 411.90 ✓
\$	CNT 98.10 ✓
\$	Sn 82.10 X
\$	Sn 59.80 X
\$	CNT 16.60 ✓
\$	Sn 80.80 X
\$	Sn 54.20 X
\$	Sn 16.60 X
\$	Bz 547.80 ✓
\$	R 114.50 X
\$	Bz 100.90 ✓
\$	Sn 76.50 X
\$	R 1,677.20 X
\$	Sn 344.70 X
\$	Sn 178.20 X
\$	Sn 277.70 X
\$	Sn 277.70 X
\$	R 82.40 ✓
\$	R 95.80 ✓
\$	Sn 145.10 X
\$	Sn 145.10 X
\$	R 254.20 X
\$	R 253.80 X
\$	Sn 611.00 X
\$	R 246.60 X

Trans-cab Auto Services Pte Ltd

AAD2006-036

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO/GST Reg. No. 201019626G

SHD 321H

2	BOOT RUBBER PLUG	\$	Sn	139.30	}	X
1	BOOT SWITCH	\$	Sn	113.00		
2	LICENCE PLATE LAMP	\$	Sn	26.30		
1	TAILLAMP RH	\$	Sn	401.40		
1	TAILLAMP PANEL RH	\$	N	401.40		
1	TAILLAMP LH	\$	Sn	401.40		
1	TAILLAMP PANEL LH	\$	N	401.40	}	✓
1	OUTER PANEL REAR (End Panel)	\$	Sn	745.80		
1	OUTER PANEL REAR (End Panel) TRIM	\$	Sn	404.56	}	X
1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	N	1,229.40		
1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21		
1	SPARE TYRE BOARD	\$	Sn	680.90		
1	EXHAUST REAR	\$	N	5,263.60		
1	EXHAUST CAP REAR	\$	N	125.40		

TOTAL	\$	17,757.07
10%	\$	1,775.71
	\$	15,981.36

Special Nett

1SET PARKING AID	\$	Shan	700.00	400.00
1SET REAR BUMPER CLIP	\$	N	69.00	—
1SET BUMPER BRACKET CTR CLIP	\$	N	35.00	—
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	N	30.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	N	35.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	N	30.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	N	35.00	X
1SET BUMPER LOWER REAR RIVET	\$	N	33.00	X
1SET BUMPER LOWER REAR CLIP	\$	N	69.00	✓
2 END PANEL SEAM SEALANT	\$	N	170.00	X
1SET BOOT FINISHER CLIP	\$	N	37.00	X
1 BOOT STICKER "Trans-cab"	\$	N	80.00	30.00
1 BOOT STICKER "6555-3333"	\$	N	80.00	30.00
1 BOOT TRIM BOARD CLIP	\$	N	45.00	X

Trans-cab Auto Services Pte Ltd

AAD2006-036

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 321H

1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	} <i>See X</i>
1 SPARE TYRE	\$	330.00	
1 TAILLAMP CLIP RH	\$	33.00	
2 REAR WINDSCREEN SEALANT	\$	150.00	
1 WINDSCREEN MOULDING	\$	180.00	
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	120.00	
1 TAILLAMP CLIP LH	\$	33.00	
1 Rear Bumper Protector	\$	120.00	
1SET Rear licence plate with holder	\$	100.00	
1SET END PANEL INSULATION PAD	\$	200.00	
TOTAL	\$	3,099.00	
TOTAL PARTS	\$	19,080.36	

LABOUR

To remove and refit rear windscreen glass to facilitate bodywork repair.

\$ *nn* 170.00 *X*

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 6,500.00 *bol*

To supply and re-do rear luggage floor panel insulation padding.

\$ *nn* 380.00 *X*

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.

\$ *nn* 380.00 *bol X*

To transfer of bootlid fittings, attachments and perform water seepage test.

\$ 170.00 *bol*

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 380.00 ** bol*

Trans-cab Auto Services Pte Ltd

AAD2006-036

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 321H

To repair and realign rear exhaust pipe.	\$	nn	170.00	X
To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	nn	170.00	X
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Rust-Proofing Of The Affected Areas.	\$		170.00	301
Putty And Spray Painting Of The Affected Portion.	\$		6,500.00	6601
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	601
To Check Electrical Lighting Concerned.	\$		170.00	201
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn	170.00	X
TOTAL	\$		16,650.00	

Over All Total \$ **35,730.36****(LUMP SUM) Repair Days****25 DAYS****4 days****LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: