

(08/11/13) wef  
ASS. REC. BY: *Marcus*

REF:

*CC4/20006400/4003*

**ASSIGNMENT**

From:

Date:

Veh No: *SL 7492K*

Yr Regn: *12 08*

Estimated Cost:

Type: *C* M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD *(TP)* / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or *CA*

To Inspect Vehicle No:

*SL 7492K*

Make: *mit Lence*

c.c. *1584*

at Workshop m/s

*Ruco 60*

Colour *Red*

A/C: Insured / Std / NI / NA

of

Sp. Reading *15-2232*

T/Radio: Insured / Std / NI / NA

Insured:

Eng/No:

Policy No.

C/No:

Claims No.

Gen. Cond: *Good* / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: *In order* / Jammed / Leaked / Burnt or

(Client's Record)

Brake: *In order* / Jammed / Leaked / Burnt or

Make of Veh:

Modi: *Nil* / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size: F: *195/50 R 15*

R:

Remark: The veh had commenced its  
repair at the time of inspection.

|     |     |
|-----|-----|
|     |     |
| N/S | O/S |
|     |     |

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

*Worder*

Bal. or Market Value:

*\$34*

Front

Rear

IDAC Accident Rpt:

Consistent? : Yes or No

R/Bal.

mm

R/Bal.

mm

GIA / PR Seen:

Consistent? : Yes or No

L/Bal.

mm

L/Bal.

mm

Est. Repairs:

*7*

days

Res.: Yes or No

D.O.A.

*14/6/20*

D.O.I.

*18/6/20*

Lum Sum:

*20*

%

3 Val.: Yes or No

Survey held at

CA / REV / REP. / 24 HRS

*LA 23386*

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

*Rear N/S.*

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*mtt 10614*

*coe 10-12-2028 Re/ Rpt. Smta*

*27/6/20 confirmed 1/5 \$6500 with John.*

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

: Site Insp (\$

) \$ + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL



Rico 60 Auto Services Pte Ltd. Blk 8, Kaki Bukit Avenue 4, #02-24  
Premier @ Kaki Bukit Singapore 415875, Email: claims@rico60.com  
Tel: 6286 6060, FAX: 6286 7060

VEHICLE NUM:  
MAKE & MODEL:  
MILEAGE:  
TYRE:  
CHASSIS NUM:

|                       |
|-----------------------|
| SJL 7492 K            |
| mitsubishi LANCER GLX |
|                       |
|                       |
|                       |

not Authorised  
2/5/2008  
7 days  
The first step is

| ATTN:        | DESCRIPTION - PARTS                |                            | QTY   | PRICE        |       |
|--------------|------------------------------------|----------------------------|-------|--------------|-------|
| NO.          |                                    |                            |       |              |       |
| 1            | REAR WINDSCREEN MOULDING           | net ✓ 121                  | 1     | 1361.00      | N ✓   |
| 2            | BOOTLID                            | 20/24 ✓ 684                | 1     | 1176.00      | N ✓   |
| 3            | BOOTLID HANDLE PANEL               | 17 X                       | 2     | NIL          | N X   |
| 4            | BOOTLID LOCK CYLINDER              | 17 X                       | 1     | 769.00       | N X   |
| 5            | BOOTLID CARPLATE LAMP (L+R)        | 11 X                       | 2     | 176.00       | N X   |
| 6            | BOOTLID LOCK                       | 7w1 ✓ 149                  | 1     | 576.00       | N ✓   |
| 7            | BOOTLID LOCK CATCH                 | 17 X                       | 1     | 171.00       | N X   |
| 8            | BOOTLID HINGE (L+R)                | 11 X                       | 2     | 176.00       | N X   |
| 9            | BOOTLID STOPPER                    | 17 X                       | 2     | 88.00        | N X   |
| 10           | BOOTLID WEATHERSTRIP               | 7w1 ✓ 197                  | 1     | 416.00       | N ✓   |
| 11           | TAIL LAMP (L+R)                    | CRA ✓ 398 x 2 = 796        | 2     | 1,246.00     | N ✓   |
| 12           | TAIL LAMP PANEL (L+R)              | N/S PPC Bul 145 524        | 2     | 1048.00      | N 1PC |
| 13           | REAR BUMPER                        | D.S ✓ 698                  | 1     | 1,171.00     | N ✓   |
| 14           | REAR BUMPER RETAINER (L+R)         | N/S Ret 17C 52 523.00      | 2     | 426.00       | N 1PC |
| 15           | REAR BUMPER REINFORCEMENT BAR      | 2w1 ✓ 171                  | 1     | 499.00       | N ✓   |
| 16           | REAR BUMPER BRACKET (L+R)          | N/S X                      | 2     | 256.00       | N X   |
| 17           | REAR BUMPER UNDERCOVER             | N/S X                      | 1     | 418.00       | N X   |
| 18           | REAR FENDER (L+R)                  | N/S 2050/AUC 1PC 795 42138 | 2     | 4276.00      | N 6C  |
| 19           | REAR FENDER INNER TRIM (L+R)       | N/S 700A 1PC 242 423       | 2     | 1,846.00     | N 1PC |
| 20           | REAR FENDER COWLING (L+R)          | N/S 700A 1PC 98 4321       | 2     | 642.00       | N 1PC |
| 21           | END PANEL                          | 3rd 907/24 ✓ 442           | 1     | 1,109.00     | N ✓   |
| 22           | END PANEL TOP GARNISH              | 7w1 ✓ 167                  | 1     | 316.00       | N ✓   |
| 23           | SPAREWHEEL PANEL                   | 2 X                        | 1     | 1,471.00     | N X   |
| 24           | SPAREWHEEL PANEL TOP BOARD         | N/S X                      | 1     | 412.00       | N X   |
| 25           | SPAREWHEEL PANEL TOP BOARD TOP MAT | 11 X                       | 1     | NIL          | N X   |
| 27           | EXHAUST GASKET                     | 17 X                       | 1     | 79.00        | N X   |
| 28           | EXHAUST BRACKET (L+R)              | 2w1 X                      | 2     | 144.00       | N X   |
|              |                                    |                            |       | P = \$11,189 |       |
|              |                                    |                            |       | SUBTOTAL     | \$ -  |
|              |                                    |                            |       | LESS 10%     | \$ -  |
|              |                                    |                            |       | PARTS TOTAL  | \$ -  |
| SPECIAL NETT |                                    |                            | QTY   | PRICE        |       |
| 1            | REAR WINDSCREEN SEALANT            | net 40                     | 1     | \$ 120.00    | 40    |
| 2            | BOOTLID SPOILER                    | 17 X                       | 1     | \$ 2,000.00  | X     |
| 3            | BOOTLID INNER TRIM CLIPS           | 17 X                       | 10    | \$ 100.00    | X     |
| 4            | REAR CARPLATE                      | 17 X                       | 1     | \$ 120.00    | X     |
| 5            | TAIL LAMP CLIPS (L+R)              | 17 X                       | 4     | \$ 80.00     | X     |
| 6            | REAR BUMPER CLIPS                  | net 59                     | 10    | \$ 100.00    | 50    |
| 7            | REAR BUMPER REVERSE SENSOR SET     | Shok 220                   | 1 set | \$ 300.00    | 220   |

| 8      | REAR BUMPER LOWER                                           | 2.5 G80 s.w        | 1   | \$    | 3,000.00  |
|--------|-------------------------------------------------------------|--------------------|-----|-------|-----------|
| 9      | REAR FENDER SEALANT                                         | 11X                | 1   | \$    | 120.00    |
| 10     | REAR FENDER INNER TRIM CLIPS                                | 11X                | 20  | \$    | 200.00    |
| 11     | REAR FENDER COWLING CLIPS                                   | 11X                | 20  | \$    | 200.00    |
| 12     | END PANEL SEALANT                                           | 11 50              | 1   | \$    | 120.00    |
| 13     | END PANEL TOP GARNISH CLIPS                                 | 11X                | 10  | \$    | 100.00    |
| 14     | SPAREWHEEL PANEL SEALANT                                    | 11X                | 1   | \$    | 120.00    |
| 15     | EXHAUST PIPE                                                | 11X                | 1   | \$    | 6,000.00  |
| 16     | EXHAUST HEAT SHIELD                                         | 11X SIN = \$1020   | 1   | \$    | 1,000.00  |
| 17     | EXHAUST CHROME TIP                                          | 11X                | 1   | \$    | 2,000.00  |
|        |                                                             |                    |     |       |           |
|        |                                                             |                    |     |       |           |
|        |                                                             | SPECIAL NETT TOTAL |     | \$    | 15,680.00 |
| LABOUR |                                                             |                    | QTY | PRICE |           |
| 1      | TO RNR ACCIDENT DAMAGE PARTS, CUT/WELD, KNOCK&REALIGN       | 1200               | 1   | \$    | 3,600.00  |
| 2      | TO PUTTY AND RESPRAY ACCIDENT AFFECTED AREA                 | 1200               | 1   | \$    | 3,000.00  |
| 3      | TO RUST PROOF ACCIDENT AFFECTED AREA                        | 80                 | 1   | \$    | 250.00    |
| 4      | TO RNR REAR WINDSCREEN                                      | 120                | 1   | \$    | 400.00    |
| 5      | TO RNR REAR BOOT MECHANISM                                  | 50                 | 1   | \$    | 400.00    |
| 6      | TO RNR REAR LUGGAGE COMPARTMENT                             | 80                 | 1   | \$    | 400.00    |
| 7      | TO RNR UPHOLSTERY, GARNISH AND ATTACHMENT PARTS             | <                  | 1   | \$    | 400.00    |
| 8      | TO RNR REVERSE SENSOR & CHECK FUNCTION.                     | 50                 | 1   | \$    | 120.00    |
| 9      | TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS                  | 11 X               | 1   | \$    | 250.00    |
| 10     | TO CHECK WIRING LAYOUT AND TAIL LAMP FUNCTION               | 20                 | 1   | \$    | 150.00    |
| 11     | TO DO DIAGNOSIS AND RESET , REPROGRAM OR CODING FAULT CODE. | 11X                | 1   | \$    | 400.00    |
| 12     | TO DO WATER LEAK TEST .                                     | 11X                | 1   | \$    | 80.00     |
| 13     | TO RNR FUEL TANK TO ASSIST WORK LOAD                        | 60                 | 1   | \$    | 250.00    |
|        |                                                             |                    |     |       |           |
|        |                                                             | L = \$2,860.       |     |       |           |
|        |                                                             |                    |     |       |           |
|        |                                                             | TOTAL              |     | \$    | 9,700.00  |
|        |                                                             | GRAND TOTAL COST   |     | \$    | 25,380.00 |
|        |                                                             |                    |     |       |           |
|        |                                                             |                    |     |       |           |

P-4757  
 102  
 P-4281.30  
 S.N-102000  
 L-2860.00  
 8161.30  
 202  
 6529