

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 19 Jun 2020

## **Preliminary Advice**

Vehicle No	: GBF6200U	Accident Date	: 14/06/2020
Make	: TOYOTA HIACE	Policy No.	: DMCVSNA00000752003
Assignment Date	: 18/06/2020	Excess	: S\$3,000.00
Date of Inspection	: 18/06/2020	Est. Duration of Repair	: 24.00
Inspection At	: HC AUTO PTE LTD (HQ) BLOCK 20 SECTOR A SIN MING IND. EST. #01-20 SINGAPORE 575678		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages N/S, N/S REAR portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	64,980.81
Revised Amount	:S\$	29,979.78
Check Items (Estimated)	:S\$	22,246.58
Total	:S\$	52,226.36

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	47,000.00
COE / PARF Rebate	:S\$	29,993.00
Salvage Value	:S\$	
Margin for Repair	:S\$	17,007.00

### **Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :
- 1) Repaier unable to provide cost price, will repair this vehicle on list price under lump sum basis.
  - 2) Please let us have your offer. Nett Value at \$28,007.00
- Please advice the above.