



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2007822
INV Date 20/11/2020
Reference CC4/FCI20006412/T1es3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SLU 5223M
Insured Veh. SHA 8747B
Claim No. D20001854MFSH
Policy No. D-20094921MFSH
Accident Date 08/04/2020
Inspection Date 15/06/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD		Ref : CC4/FCI20006412/T1es3q2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 20-11-2020		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 8747B	Veh. Inspected	SLU 5223M	
Policy No.	D-20094921MFSH	Coverage (\$)	0.00	
Claim No.	D20001854MFSH	Excess (\$)	0.00	
Assign From	ERIC	Assign Date	15/06/2020	
2. Vehicle Particulars & Condition				
Make & Model	CITROEN GRAND PICASSO	c.c	1560	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	VF73ABHZTHJ776818	Colour	WHITE	
Odometer	43712	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/60 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/60 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/04/2020	Inspection Date	15/06/2020	
Survey held at	CYCLE & CARRIAGE FRANCE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLU 5223M

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	C&C BADGE (SN)	NECESSARY	40.00	40.00
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
1	REAR BUMPER (SN)	DEFORMED	910.00	910.00
1	BUMPER BRACKET (SN)	BENT	317.00	317.00
1	BUMPER SKIRT (SN)	CUT	331.00	331.00
1	SET BRACKET (SN)	NOT NECESSARY	107.00	-
1	BRACKET SET LAT (SN)	NOT NECESSARY	107.00	-
1	BUMPER BRACKET (SN)	BENT	314.00	314.00
1	STIFFENER LH (SN)	NOT NECESSARY	62.00	-
1	STIFFENER RH (SN)	NOT NECESSARY	62.00	-
1	TAILGATE (SN)	NOT NECESSARY	2,860.00	-
1	TLGT EXT PANEL (SN)	DEFORMED	581.00	581.00
1	TAILGATE MOULDING (SN)	NOT NECESSARY	335.00	-
1	TAIL-LIGHT LH (SN)	NOT NECESSARY	1,165.00	-
1	TAIL-LIGHT RH (SN)	NOT NECESSARY	1,165.00	-
1	TAIL-LIGHT LH COMPLEMENTAIRE (SN)	NOT NECESSARY	178.00	-
1	TAIL-LIGHT RH COMPLEMENTAIRE (SN)	NOT NECESSARY	178.00	-
1	SENSOR (SN)	NOT NECESSARY	139.00	-
1	BADGE (SN)	NECESSARY	42.00	42.00
1	BADGE (SN)	NECESSARY	60.00	60.00
1	BADGE (SN)	NECESSARY	88.00	88.00
			9,091.00	2,703.00
<u>LABOUR</u>				
	WASH,WAX ,CLEAN & VACUUM.	NOT NECESSARY	23.00	-
	RENEW RR BUMPER & TAILGATE LWR PNL REPAIR RR END PNL.		3,000.00	1,200.00
	RESPRAY RR BUMPER ,RR END PNL ,TAILGATE & TAILGATE LWR PNL .		1,680.00	840.00
	REMOVE & REFIT RR FLR BOARD ,TRIM & CARPET TO FACILITATE REPAIR .		300.00	300.00
	CHECK WIRING ELECTRICAL SYSTEM.		50.00	30.00

Report Ref No. CC4/FCI20006412/T1es3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.		300.00	300.00
	APPLY ANTI CORROSION ON AFFECTED AREAS.	NOT NECESSARY	80.00	-
	SUPPLY RR NUMBER PLATE WITH CASING.	NOT NECESSARY	80.00	-
	REMOVE & REFIT REVERSE SENSOR .		100.00	80.00
			5,613.00	2,750.00
GRAND TOTAL			14,704.00	5,453.00

RECOMMENDED COST OF REPAIRS				5,453.00
------------------------------------	--	--	--	-----------------

Report Ref No. CC4/FCI20006412/T1es3q2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 5223M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLU 5223M

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

