

ESTIMATE

Company Reg No. 200609327M
 GST Reg No. MR-8500111-X

Invoice Name & Address				Owner Name & Vehicle Info			
Chan Lay Cheng				Cust No/Name / CHAN LAY CHENG			
50 LORONG M TELOK KURAU				Reg No/Reg Date SLU5223M / 05/12/2017			
#05-07				Date In/Mileage / 0			
SINGAPORE 425342				Chassis No VF73ABHZTHJ776818			
Contact No Mobile: 96695270				Engine No 10JBHD3087454			
				Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML			
				Colour/Trim WPP BLANC BANQUISE / IXF YATAGO GREY			
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00073	Cash	13/04/2020/ 15:23		265 / AndreChow	15296		
Description of Goods / Services					Qty	Unit Price	Disc% Amount
I WWCV							23.00
Wash, Wax, Clean & Vacuum							
E PNT88000							3000.00
RENEW RR BUMPER & TAILGATE LWR PNL							
REPAIR RR END PNL							
E PNT98000							1680.00
RESPRAY RR BUMPER, RR END PNL, TAILGATE & TAILGATE LWR PNL							
E PNT88000							300.00
REMOVE & REFIT RR FLR BOARD, TRIM & CARPET TO FACILITATE REPAIR							
A 54900099							50.00
CHECK WIRING ELECTRICAL SYSTEM							
A 10028901							300.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							
M SUNDRY							80.00
APPLY ANTI CORROSION ON AFFECTED AREAS							
M SUNDRY							80.00
SUPPLY RR NUMBER PLATE WITH CASING							
E PNT88000							100.00
REMOVE & REFIT REVERSE SENSOR							
M SUNDRY							40.00
SUPPLY C&C BADGE							
M SUNDRY							50.00
Sundries							
M REAR BUMPER					1.00	910.00	0.00 910.00
M BUMPER BRACKET					1.00	317.00	0.00 317.00
M BUMPER SKIRT					1.00	331.00	0.00 331.00
M BRACKET SET					1.00	107.00	0.00 107.00
M BRACKET SET LAT					1.00	107.00	0.00 107.00
M BUMPER BRACKET					1.00	314.00	0.00 314.00
M STIFFENER LH					1.00	62.00	0.00 62.00
M STIFFENER RH					1.00	62.00	0.00 62.00
M TAILGATE					1.00	2860.00	0.00 2860.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

ESTIMATE

Company Reg No. 200609327/M
GST Reg No. MR 8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Chan Lay Cheng		Cust No/Name / CHAN LAY CHENG	
50 LORONG M TELOK KURAU		Reg No/Reg Date SLU5223M / 05/12/2017	
#05-07		Date In/Mileage / 0	
SINGAPORE 425342		Chassis No VF73ABHZTHJ776818	
Contact No Mobile: 96695270		Engine No 10JBHD3087454	
		Make/Model CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML	
		Colour/Trim WPP BLANC BANQUISE / IXF YATAGO GREY	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00073	Cash	13/04/2020/ 15:23		265 / AndreChow	15296		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M	TLGT EXT PANEL			1.00	581.00	0.00	581.00
M	TLGATE MOULDING			1.00	335.00	0.00	335.00
M	TAIL-LIGHT LH			1.00	1165.00	0.00	1165.00
M	TAIL-LIGHT RH			1.00	1165.00	0.00	1165.00
M	TAIL-LIGHT LH COMPLEMENTAIRE			1.00	178.00	0.00	178.00
M	TAIL-LIGHT RH COMPLEMENTAIRE			1.00	178.00	0.00	178.00
M	SENSOR			1.00	139.00	0.00	139.00
M	BADGE			1.00	42.00	0.00	42.00
M	BADGE			1.00	60.00	0.00	60.00
M	BADGE			1.00	88.00	0.00	88.00

2643

Estimate

2810

2643

\$5453#

4 days

SURVEYOR NAME: Taufik 97495791SURVEYOR SIGNATURE: [Signature]DATE: 15/6/20 @ 1220 WPREMARKS: Resurvey before paint
taufik@khams.com

0.4 days

<p>LEK Auto Consultant</p> <p>the Repairer of the fo</p> <ul style="list-style-type: none"> To resurvey before/after To display damaged parts Prices are subject to Third party survey is on a "W.I." Legal modification(s) is Elementary item(s) must Subject to final approval from <p>Warranted by Repairer</p> <p>re:</p>	<p>Validity</p> <p>Time</p> <p>Insurance</p> <p>Prejudice basis</p> <p>Surveyed and</p> <p>Finance Company</p>
--	--

Confirm & accepted by

Parts	9,001.00
Labour	5,430.00
Standard Menu	23.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	250.00
Total(w/o GST)	14,704.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.