



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

ESTIMATE

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

Invoice Name & Address				Owner Name & Vehicle Info		
Chan Lay Cheng				Cust No/Name	/ CHAN LAY CHENG	
50 LORONG M TELOK KURAU				Reg No/Reg Date	SLU5223M / 05/12/2017	
#05-07				Date In/Mileage	/ 0	
SINGAPORE 425342				Chassis No	VF73ABHZTHJ776818	
Contact No Mobile: 96695270				Engine No	10JBHD3087454	
				Make/Model	CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML	
				Colour/Trim	WPP BLANC BANQUISE / IXF YATAGO GREY	
Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
CSM00073	Cash	13/04/2020/ 15:23		265 / AndreChow	15296	
Description of Goods / Services				Qty	Unit Price	Disc% Amount
I WWCV						23.00
Wash, Wax, Clean & Vacuum						
E PNT88000						1200. 3000.00
RENEW RR BUMPER & TAILGATE LWR PNL						
REPAIR RR END PNL						
E PNT98000						840. 1680.00
RESPRAY RR BUMPER, RR END PNL, TAILGATE & TAILGATE LWR PNL						
E PNT88000						? 300.00
REMOVE & REFIT RR FLR BOARD, TRIM & CARPET TO FACILITATE REPAIR						
A 54900099						30. 50.00
CHECK WIRING ELECTRICAL SYSTEM						
A 10028901						✓ 300.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST						
USING HI-SCAN PRO TEST						
M SUNDRY						X 80.00
APPLY ANTI CORROSION ON AFFECTED AREAS						
M SUNDRY						X 80.00
SUPPLY RR NUMBER PLATE WITH CASING						
E PNT88000						80. 100.00
REMOVE & REFIT REVERSE SENSOR						
M SUNDRY						rel ✓ 40.00
SUPPLY C&C BADGE						20. 50.00
M SUNDRY						
Sundries						
M REAR BUMPER				1.00	910.00	0.00 ✓ 910.00
M BUMPER BRACKET				1.00	317.00	0.00 ? 317.00
M BUMPER SKIRT				1.00	331.00	0.00 at ✓ 331.00
M BRACKET SET				1.00	107.00	0.00 ? 107.00
M BRACKET SET LAT				1.00	107.00	0.00 ? 107.00
M BUMPER BRACKET				1.00	314.00	0.00 ? 314.00
M STIFFENER LH				1.00	62.00	0.00 ? 62.00
M STIFFENER RH				1.00	62.00	0.00 ? 62.00
M TAILGATE				1.00	2860.00	0.00 ? 2860.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE FRANCE PTE. LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 6568 4501 Fax: (65) 6565 1240



CITROËN

ESTIMATE

Company Reg No. 200609327M
GST Reg No. MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
Chan Lay Cheng		Cust No/Name	/ CHAN LAY CHENG
50 LORONG M TELOK KURAU		Reg No/Reg Date	SLU5223M / 05/12/2017
#05-07		Date In/Mileage	/ 0
SINGAPORE 425342		Chassis No	VF73ABHZTHJ776818
Contact No Mobile: 96695270		Engine No	10JBHD3087454
		Make/Model	CIT/GC4P 1.6 BLUEHDI EAT6 INTENSIVE ML
		Colour/Trim	WPP BLANC BANQUISE / IXF YATAGO GREY

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00073	Cash	13/04/2020/ 15:23		265 / AndreChow	15296
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M	TLGT EXT PANEL	1.00	581.00	0.00	581.00
M	TLGATE MOULDING	1.00	335.00	0.00	335.00
M	TAIL-LIGHT LH	1.00	1165.00	0.00	1165.00
M	TAIL-LIGHT RH	1.00	1165.00	0.00	1165.00
M	TAIL-LIGHT LH COMPLEMENTAIRE	1.00	178.00	0.00	178.00
M	TAIL-LIGHT RH COMPLEMENTAIRE	1.00	178.00	0.00	178.00
M	SENSOR	1.00	139.00	0.00	139.00
M	BADGE	1.00	42.00	0.00	42.00
M	BADGE	1.00	60.00	0.00	60.00
M	BADGE	1.00	88.00	0.00	88.00

Estimate

SURVEYOR NAME: Taufik 97495749

SURVEYOR SIGNATURE: Taufik

DATE: 15/6/20 12:20 WP

REMARKS: Resurvey before paint
taufik@lkkauto.com
0.4 days

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) clearly
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and subject to final approval from Insurance Company

acknowledged by Repairer
Date:

Confirm & accepted by

Parts	9,001.00
Labour	5,430.00
Standard Menu	23.00
Specialist Job	0.00
Diagnostics Job	0.00
Sundry/Others	250.00
Total (w/o GST)	14,704.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.