

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

17 JUN 2020

PART

- 1 REAR BUMPER
- 1 REAR BUMPER RE-INFORCEMENT
- 1 REAR BUMPER TOWING COVER
- 1 GUARD, REAR BUMPER, CENTER
- 1 ANTENNA, ELECTRICAL KEY
- 1 REAR BUMPER SIDE RETAINER LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REAR BUMPER SIDE RH
- 1 REAR BUMPER SIDE LH
- 1 REAR TAILGATE
- 1 REAR TAILGATE OUTER GARNISH
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 BOARD, BACK DOOR TRIM
- 1 PANEL ASSY, BACK DOOR TRIM, UPPER
- 1 GARNISH, BACK DOOR SIDE, LH
- 1 GARNISH, BACK DOOR SIDE, RH
- 1 REAR TAILGATE WEATHERSTRIP
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 TAILLAMP LOWER RH
- 1 TAILLAMP UPPER RH
- 1 TAILLAMP LOWER LH
- 1 TAILLAMP UPPER LH
- 1 PANEL ASSY, DECK TRIM SIDE, RH
- 1 BOX, DECK FLOOR, RH
- 1 BOX, DECK FLOOR, LH
- 1 BOARD, REAR FLOOR, NO.1
- 1 PANEL ASSY, DECK TRIM SIDE, LH

AAD2006-038*Not Authorized**Resurvey B4 paint***SHD 5986G**

JTDKB3FU403075667

TOYOTA

PRIUS

16.6.2020

CHINA TAIPING

1/11/2018

LIST

\$	Bu	442.60	✓
\$		332.70	?
\$	Sn	15.40	X
\$	Bu 100	576.30	✓
\$	Sn	72.00	X
\$	Sn	116.50	X
\$	Sn	117.70	X
\$	Sn	123.70	X
\$	Sn	123.70	X
\$	Bu	1,147.80	✓
\$	CM	925.60	✓
\$	MT	64.50	✓
\$		259.20	?
\$		225.20	?
\$	Sn	52.10	X
\$	Sn	95.60	X
\$	Sn	95.60	X
\$	Sn	372.30	X
\$	Sn	650.30	} X
\$	Sn	502.00	
\$	Sn	451.80	
\$	Sn	502.00	
\$	Sn	443.30	
\$	Sn	355.90	
\$	Sn	313.60	
\$	Sn	313.00	
\$	Sn	519.00	
\$	Sn A	355.90	✓

AAD2006-038

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G

1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	Sm	56.50	
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	Sm	56.50	
1	TAILLAMP PANEL LH	\$	R	445.50	
1	TAILLAMP PANEL RH	\$	R	445.50	
1	COVER, FLOOR UNDER, NO.1	\$	Sm	175.10	
1	COVER, FLOOR UNDER, NO.2	\$	Sm	241.90	
1	COVER, REAR FLOOR	\$	R	229.90	
1	COVER, DECK TRIM, REAR	\$	Sm	126.70	
1	COVER ASSY, TONNEAU	\$	Sm	979.40	X
1	PAN, REAR FLOOR	\$	R	583.40	
1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	R	196.50	
1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	R	196.50	
1	EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	R	78.30	
1	EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	R	78.30	
1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$	Sm	467.00	
1	COVER, BACK DOOR LOCK	\$	Sm	30.20	
1	SWITCH ASSY, BACK DOOR OPENER	\$	Sm	179.10	
1	STRIKER ASSY, BACK DOOR LOCK	\$	Sm	25.80	
1	SPOILER, SUB ASSY, REAR	\$	wap/cm	1,575.40	✓
1	LAMP SUB ASSY, LICENSE PLATE	\$	cm	287.80	✓
1	LAMP SET, STOP CENTER	\$	Sm	192.30	X
1	GLASS, BACK WINDOW FIX	\$	Shorted	761.40	✓
1	DAM, BACK DOOR GLASS ADHESIVE, NO.2	\$	m	28.90	✓
1	MOULDING, BACK WINDOW, LOWER NO.2	\$	m	23.60	✓
1	MOULDING, BACK WINDOW, OUTSIDE LH NO.2	\$	m	30.90	✓
1	MOULDING, BACK WINDOW, OUTSIDE RH NO.2	\$	m	30.90	✓
1	SPACER, BACK WINDOW GLASS	\$	m	10.20	✓
1	WIRE, BACK DOOR, NO.2	\$	Seq	294.40	
1	WIRE, LUGGAGE ROOM, NO.3	\$	Sm	170.70	
1	WIRE, BACK DOOR, NO.1	\$	Sm	247.40	
1	STAY ASSY, BACK DOOR, LH	\$	Sm	242.50	
1	STAY ASSY, BACK DOOR, RH	\$	Sm	242.50	X
1	HINGE ASSY, BACK DOOR, LH	\$	Sm	61.00	
1	HINGE ASSY, BACK DOOR, RH	\$	Sm	61.00	

TOTAL \$ 18,418.30

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G**AAD2006-038**

25%	\$	4,604.58
	\$	13,813.73

Special Nett

1SET PARKING AID	\$	Rs 700.00	220sn
1SET REAR BUMPER CLIP	\$	Rs 75.00	✓
2 REAR WINDSCREEN SEALANT	\$	Rs 150.00	80sn
1 WINDSCREEN MOULDING	\$	Rs 180.00	✓
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	Rs 120.00	30sn
1 REAR TAILGATE TOYOTA LOGO	\$	Rs 47.00	✓
1 REAR TAILGATE WORDING 'PRIUS' }	\$	Rs 52.90	✓
1 REAR TAILGATE WORDING 'HYBRID' }	\$	Rs 53.50	✓
1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	Rs 80.00	30sn
1 REAR TAILGATE STICKER '6555-3333'	\$	Rs 80.00	30sn
1 REAR BUMPER PROTECTOR	\$	Rs 120.00	30sn
1SET REAR RH BUMPER RETAINER CLIP	\$	Rs 38.00	} X
1 REAR NUMBER PLATE WITH HOLDER	\$	Rs 200.00	
1SET REAR LH BUMPER RETAINER CLIP	\$	Rs 38.00	
1SET END PANEL INNER TRIM CLIP	\$	Rs 35.00	
1SET END PANEL INSULATION PAD	\$	Rs 200.00	
2 END PANEL SEAM SEALANT	\$	Rs 170.00	
1SET TAILLAMP LOWER CLIP	\$	Rs 35.00	
1SET TAILLAMP UPPER CLIP	\$	Rs 35.00	
1SET REAR BOOT TRIM BOARD CLIP	\$	Rs 45.00	
1SET REAR BOOT OUTER GARNISH CLIP	\$	Rs 35.00	
1 WHEEL RIM COVER	\$	Rs 211.50	} X
1 TYRE 195/65/15	\$	Rs 350.00	
1 WHEEL, RIM	\$	Rs 1,879.40	
1SET REAR SPOILER CLIP	\$	Rs 45.00	✓

TOTAL	\$	4,975.30
--------------	----	-----------------

TOTAL PARTS	\$	18,789.03
--------------------	----	------------------

LABOUR

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$	380.00	50h
----	--------	-----

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G**AAD2006-038**

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	5001
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	501
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Remove And Refit Rear (Big) W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	1201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To Remove And Refit Rear (Small) W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	601

Trans-cab Auto Services Pte Ltd

AAD2006-038

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G

To supply and re-do rear end panel insulation padding. \$ ^{^^} 380.00 XTo transfer of tire, rim and on wheel balancing. \$ ^{^^} 170.00 X**TOTAL \$ 18,480.00****Over All Total \$ 37,269.03****(PART-BY-PART) Repair Days**~~30~~ DAYS

3 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: