

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G**AAD2006-038***Not Authorized**Recovery Bk paint***87323.35**

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

17 JUN 2020**SHD 5986G**

JTDKB3FU403075667

TOYOTA

PRIUS

16.6.2020

CHINA TAIPING

1/11/2018

PART

- 1 REAR BUMPER
- 1 REAR BUMPER RE-INFORCEMENT
- 1 REAR BUMPER TOWING COVER
- 1 GUARD, REAR BUMPER, CENTER
- 1 ANTENNA, ELECTRICAL KEY
- 1 REAR BUMPER SIDE RETAINER LH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 REAR BUMPER SIDE RH
- 1 REAR BUMPER SIDE LH
- 1 REAR TAILGATE
- 1 REAR TAILGATE OUTER GARNISH
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 BOARD ASSY, BACK DOOR TRIM
- 1 BOARD, BACK DOOR TRIM
- 1 PANEL ASSY, BACK DOOR TRIM, UPPER
- 1 GARNISH, BACK DOOR SIDE, LH
- 1 GARNISH, BACK DOOR SIDE, RH
- 1 REAR TAILGATE WEATHERSTRIP
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 TAILLAMP LOWER RH
- 1 TAILLAMP UPPER RH
- 1 TAILLAMP LOWER LH
- 1 TAILLAMP UPPER LH
- 1 PANEL ASSY, DECK TRIM SIDE, RH
- 1 BOX, DECK FLOOR, RH
- 1 BOX, DECK FLOOR, LH
- 1 BOARD, REAR FLOOR, NO.1
- 1 PANEL ASSY, DECK TRIM SIDE, LH

LIST

\$	<i>Bu</i>	442.60	✓
\$	<i>B</i>	332.70	✓
\$	<i>S</i>	15.40	X
\$	<i>Bu / Bu</i>	576.30	✓
\$	<i>S</i>	72.00	X
\$	<i>S</i>	116.50	X
\$	<i>S</i>	117.70	X
\$	<i>S</i>	123.70	X
\$	<i>bu</i>	123.70	X
\$	<i>B</i>	1,147.80	✓
\$	<i>CM</i>	925.60	✓
\$	<i>MY</i>	64.50	✓
\$	<i>mycm</i>	259.20	✓
\$	<i>S</i>	225.20	X
\$	<i>S</i>	52.10	X
\$	<i>S</i>	95.60	X
\$	<i>S</i>	95.60	X
\$	<i>S</i>	372.30	X
\$	<i>R</i>	650.30	} X
\$	<i>S</i>	502.00	
\$	<i>S</i>	451.80	
\$	<i>S</i>	502.00	
\$	<i>S</i>	443.30	
\$	<i>R</i>	355.90	
\$	<i>R</i>	313.60	
\$	<i>R</i>	313.00	
\$	<i>R</i>	519.00	
\$	<i>S</i> <i>A</i>	355.90	

Trans-cab Auto Services Pte Ltd**AAD2006-038**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G

1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER LH	\$	<i>Sm</i>	56.50	}	X
1	MOULDING, BACK DOOR OUTSIDE GARNISH, LOWER RH	\$	<i>Sm</i>	56.50		
1	TAILLAMP PANEL LH	\$	<i>R</i>	445.50		
1	TAILLAMP PANEL RH	\$	<i>R</i>	445.50		
1	COVER, FLOOR UNDER, NO.1	\$	<i>Sm</i>	175.10		
1	COVER, FLOOR UNDER, NO.2	\$	<i>Sm</i>	241.90		
1	COVER, REAR FLOOR	\$	<i>R</i>	229.90		
1	COVER, DECK TRIM, REAR	\$	<i>Sm</i>	126.70		
1	COVER ASSY, TONNEAU	\$	<i>Sm</i>	979.40		
1	PAN, REAR FLOOR	\$	<i>R</i>	583.40		
1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, RH	\$	<i>R</i>	196.50		
1	EXTENSION, REAR FLOOR PAN TO QUARTER PANEL, LH	\$	<i>R</i>	196.50		
1	EXTENSION, REAR FLOOR SIDE PANEL, RH	\$	<i>R</i>	78.30		
1	EXTENSION, REAR FLOOR SIDE PANEL, LH	\$	<i>R</i>	78.30		
1	LOCK ASSY, BACK DOOR, W/COURTESY LAMP SWITCH	\$	<i>Sm</i>	467.00		
1	COVER, BACK DOOR LOCK	\$	<i>Sm</i>	30.20		
1	SWITCH ASSY, BACK DOOR OPENER	\$	<i>Sm</i>	179.10		
1	STRIKER ASSY, BACK DOOR LOCK	\$	<i>Sm</i>	25.80		
1	SPOILER, SUB ASSY, REAR	\$	<i>wap/cm</i>	1,575.40	}	✓
1	LAMP SUB ASSY, LICENSE PLATE	\$	<i>cm</i>	287.80		
1	LAMP SET, STOP CENTER	\$	<i>Sm</i>	192.30		
1	GLASS, BACK WINDOW FIX	\$	<i>shorten</i>	761.40		
1	DAM, BACK DOOR GLASS ADHESIVE, NO.2	\$	<i>me</i>	28.90		
1	MOULDING, BACK WINDOW, LOWER NO.2	\$	<i>me</i>	23.60	}	✓
1	MOULDING, BACK WINDOW, OUTSIDE LH NO.2	\$	<i>me</i>	30.90		
1	MOULDING, BACK WINDOW, OUTSIDE RH NO.2	\$	<i>me</i>	30.90		
1	SPACER, BACK WINDOW GLASS	\$	<i>me</i>	10.20		
1	WIRE, BACK DOOR, NO.2	\$	<i>Sm</i>	294.40		
1	WIRE, LUGGAGE ROOM, NO.3	\$	<i>Sm</i>	170.70	}	X
1	WIRE, BACK DOOR, NO.1	\$	<i>Sm</i>	247.40		
1	STAY ASSY, BACK DOOR, LH	\$	<i>Sm</i>	242.50		
1	STAY ASSY, BACK DOOR, RH	\$	<i>Sm</i>	242.50		
1	HINGE ASSY, BACK DOOR, LH	\$	<i>Sm</i>	61.00	}	X
1	HINGE ASSY, BACK DOOR, RH	\$	<i>Sm</i>	61.00		

TOTAL \$ 18,418.30

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G**AAD2006-038**

25%	\$	4,604.58
	\$	13,813.73

Special Nett

1SET PARKING AID	\$	Pa	700.00	220sa
1SET REAR BUMPER CLIP	\$	na	75.00	65sa
2 REAR WINDSCREEN SEALANT	\$	na	150.00	80sa
1 WINDSCREEN MOULDING	\$	na	180.00	
1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	120.00	30sa
1 REAR TAILGATE TOYOTA LOGO	\$	na	47.00	+ 7mm
1 REAR TAILGATE WORDING 'PRIUS'	\$	na	52.90	+ 7mm
1 REAR TAILGATE WORDING 'HYBRID'	\$	na	53.50	+ 7mm
1 REAR TAILGATE STICKER 'TRANS-CAB'	\$	na	80.00	30sa
1 REAR TAILGATE STICKER '6555-3333'	\$	na	80.00	30sa
1 REAR BUMPER PROTECTOR	\$	na	120.00	30sa
1SET REAR RH BUMPER RETAINER CLIP	\$	na	38.00	X
1 REAR NUMBER PLATE WITH HOLDER	\$	sa	200.00	
1SET REAR LH BUMPER RETAINER CLIP	\$	na	38.00	
1SET END PANEL INNER TRIM CLIP	\$	na	35.00	
1SET END PANEL INSULATION PAD	\$	na	200.00	
2 END PANEL SEAM SEALANT	\$	na	170.00	
1SET TAILLAMP LOWER CLIP	\$	na	35.00	
1SET TAILLAMP UPPER CLIP	\$	na	35.00	
1SET REAR BOOT TRIM BOARD CLIP	\$	na	45.00	
1SET REAR BOOT OUTER GARNISH CLIP	\$	na	35.00	
1 WHEEL RIM COVER	\$	sa	211.50	✓
1 TYRE 195/65/15	\$	sa	350.00	
1 WHEEL, RIM	\$	sa	1,879.40	
1SET REAR SPOILER CLIP	\$	na	45.00	

TOTAL \$ 4,975.30**TOTAL PARTS \$ 18,789.03****LABOUR**

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 380.00 50h

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986G**AAD2006-038**

Putty And Spray Painting Of The Affected Portion.	\$	7,500.00	8801
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	7,500.00	5001
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To transfer of Tailgate fittings, attachments and perform water seepage test.	\$	170.00	601
To reinstall rear bumper parking sensor.	\$	170.00	501
To Rust-Proofing Of The Affected Areas.	\$	nn 170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn 380.00	X
To Remove And Refit Rear (Big) W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	1201
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	nn 380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	nn 220.00	X
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To Remove And Refit Rear (Small) W/Screen Glass To Facilitate Bodywork Repair.	\$	170.00	601

Trans-cab Auto Services Pte Ltd**AAD2006-038**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5986GTo supply and re-do rear end panel insulation padding. \$ ⁿⁿ 380.00 XTo transfer of tire, rim and on wheel balancing. \$ ⁿⁿ 170.00 X**TOTAL \$ 18,480.00****Over All Total \$ 37,269.03****(PART-BY-PART) Repair Days ²⁰ DAYS***3 days*LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: