

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006424/GRA3Q2

Date: 22/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700049957

Claimant
Vehicle No : GBE8100S **Insured Vehicle No :** SLS1498Z

Date of Loss: 13/06/2020 Nature of Claim: TP Claim No: 8600541961SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE8100S		
Make & Model:	LAND ROVER DEFENDER 90, 2.2 D (M)	Engine No:	150917113422DT224
Reg. Date:	18/05/2016 (Man. Year: 2015)	Chassis No:	SALLDWBP7GA483888
Colour:	Grey	Odometer:	28218 km
Engine Capacity:	2198 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/85R16	Rear Tyre Size:	235/85R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,074.00	919.60	2,154.40	70.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	530.00	470.00	47.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,074.00	1,449.60	2,624.40	64.42
Approved Total (Overridden) (S\$)		1,150.00		
(S\$)	4,074.00	1,150.00	2,924.00	71.77
+ GST 7.00/7.00% (S\$)	285.18	80.50	204.68	71.77
Nett Amount (S\$)	4,359.18	1,230.50	3,128.68	71.77
+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00		
Nett Liability (S\$)		1,410.50		

INSPECTION

Date of Assignment: 18/06/2020

Date Inspected: 25/06/2020 Inspected At:

Kian Teong Auto Centre (HQ)
BLK 176 SIN MING DRIVE #01-08
SIN MING AUTOCARE
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: XING GUO QIANG**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*WHEEL COVER SPARE WHEEL	Not Necessary	795.00 F	*- FL
2	1		*LAMP COVER METAL GRILL	Missing	395.00 F	*395.00 FL
3	1		*REAR RH STOP LAMP GUARD	Broken	68.00 F	*68.00 FL
4	1		*REAR RH SIGNAL LAMP GUARD	Broken	58.00 F	*58.00 FL
5	1		*REAR RH MUD GUARD	Bent	285.00 F	*180.00 FL
6	1		*EMBLEM L.R	Necessary	98.00 F	*98.00 FL
7	1		*L.R DEFENDER STICKERS	Necessary	45.00 F	*45.00 FL
8	1		*SET REVERSE SENSOR	Damaged	280.00 FS	*150.00 FS
9	1		*70KM/HR STICKER	Necessary	1,050.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	3,074.00	1,004.00
- List Item Discount on L Items 0.00/10.00% (\$)	0.00	84.40
Total Parts (\$)	3,074.00	919.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PROVISION OF LABOUR,TOOLS AND CONSUMABLES.TO REMOVE AND CHANGE ALL DAMAGED PARTS.TO KNOCK AND REPAIR DAMAGED PARTS	New	380.00	250.00
2	TO SPRAY PAINT ALL DAMAGED PARTS	New	500.00	250.00
3	TO CHECK ALL ELECTRICAL WIRING	New	120.00	30.00
Gross Labour Cost (S\$)			1,000.00	530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >