

ESTIMATE

DATE : 17/6/2020
ACC DATE : 03/4/2020
POLICY NO :
SHEET NO. 1 OF 2 SHEET
DMCVSN1835581901

Attention: Motor Claim Department

RE : VEHICLE NO : XD8414G (KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD)

S/NO.	QTY	DESCRIPTION	UNIT PRICE S\$	AMOUNT S\$
1	1	FRONT BUMPER		4,043.40
2	1	FRONT BUMPER REINFORCEMENT		890.00
3	1	FRONT BUMPER TOP PAD		458.00
4	1	FRONT BUMPER TOP PAD CENTER GARNISH		245.00
5	1	FRONT BUMPER CENTER GRILLE		487.90
6	1	FRONT BUMPER SIDE PAD (LH)		457.60
7	1	FRONT BUMPER LOWER PAD (MID LH)		475.00
8	1	FRONT BUMPER LOWER PAD OUTER COVER (fay h, h) - BR		326.50
9	1	FRONT BUMPER LOWER GRILLE		475.00
10	1	FRONT BUMPER LOWER STEP PLATE		370.00
11	1	FRONT BUMPER LOWER STEP PLATE TOP CHROME		245.60
12	1	FRONT BUMPER TOWING COVER		42.00
13	1	FRONT BUMPER FOG LAMP LH		420.00
14	1	FRONT BUMPER FOG LAMP COVER LH		120.00
15	1	FRONT SIDE BUMPER LH (Head & side gr.) - BR		476.00
16	1	FRONT HEAD LAMP LH		375.00
17	1	FRONT HEAD LAMP RIM LH		195.70
18	1	FRONT PARKING LAMP LH		274.00
19	1	FRONT SIGNAL LAMP LH		252.00
20	1	FRONT DOOR BOTTOM STEP GARNISH LH		450.00
21	1	FRONT DOOR BOTTOM STEP GARNISH SIDE COVER LH		680.00
22	1	FRONT DOOR PILLAR LH INNER		820.00
23	1	FRONT DOOR PILLAR LH CENTER		850.00
24	1	FRONT DOOR LH		3,300.00
25	1	FRONT DOOR WINDOW GLASS		650.00
26	1	FRONT DOOR OUTER MOULDING		217.00
27	1	FRONT DOOR OUTER GARNISH		98.00
28	1	FRONT DOOR OUTER HANDLER		244.00
29	1	FRONT DOOR OUTER KEYLOCK		110.00
30	2	FRONT DOOR HINGE LH	90.00	180.00
31	1	FRONT DOOR JACKER		160.00
32	1	FRONT DOOR INNER LOCK		320.00
33	1	FRONT DOOR LOCK CATCH		46.00
34	1	FRONT DOOR LOCK WEATHER STRIP		210.00
35	1	FRONT DOOR INNER TRIM		317.00
36	1	FRONT DOOR INNER HANDLER		210.00
37	1	FRONT DOOR REGULATOR MOTOR		790.00
38	1	FRONT DOOR GEARLINKAGE		220.00
39	1	FRONT TOP STEP BOARD LH		576.00
40	1	FRONT BOTTOM STEP BOARD LH		450.00
41	1	FRONT SIDE STEP BOARD GARNISH LH		370.00
42	1	FRONT STEP PLATE LH		380.00
43	1	FRONT SIDE MIRROR HOUSING LH		670.00
44	1	FRONT SIDE MIRROR HOUSING BOTTOM BRACKET LH		90.00
45	1	FRONT SIDE MIRROR COVER LH		210.00
46	1	FRONT SIDE MIRROR BOTTOM COVER LH		150.00
47	1	FRONT SIDE MIRROR GLASS LH		140.00
48	1	FRONT SIDE MIRROR BOTTOM GLASS LH		90.00
49	1	FRONT FENDER MUDGUARD REAR LH		489.00
50	1	REAR FENDER LH		

Side mirror bracket (LH) - BT

\$890 / 1,314.00

16,797.70 \$ 26,429.70

- 10%
15,117.93



VFX Auto Pte Ltd
26 Chao Feng Road
Singapore 619977
Email: contact@vfxauto.com.sg
Tel: 64552557 Fax: 65625669
UET / GST REG NO: 201530761R

ESTIMATE

DATE: 17/6/2020
ACC DATE: 03/4/2020
POLICY NO: DMCVSN1835581901
SHEET NO: 1 OF 2 SHEET

Attention: Motor Claim Department

RE: VEHICLE NO: XD8414G (KOK TONG TRANSPORT & ENGINEERING WORKS PTE LTD)

S/NO.	QTY	DESCRIPTION	UNIT PRICE	AMOUNT S\$
1	1	SPECIAL NET		
1	1	FRONT TYRE LH X/A		\$ 400.00 X
2	1	FRONT RIM LH X/A		\$ 500.00 X
				\$ 900.00

S/NO.	QTY	LABOUR & MISCELLANEOUS	AMOUNT S\$
-------	-----	------------------------	------------

1 To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments

4,000.00

2000

2 To spray paint replaced/repainted body panels inclusive of preparatory works and painting materials

2,000.00

1000

3 To check and refit wiring

600.00

250

4 To reset and diagnosis fault code

700.00

150

5 To dismantle and refit front door part

150.00

100

6 To dismantle and refit interior ,carpet and cushion

600.00

? X

\$ 8,050.00

3500

GRAND TOTAL

\$ 35,379.70

ISSUED BY

KOH WENG SHENG



VERIFIED BY

KEN TAN

ESTIMATE CONFIRMED AND ACCEPTED BY

NAME, SIGNATURE, DATE SIGNED

P- 15,117.93

L- 3500

18,617.93

L/S - 14,894.34

= 14,900.99

Steve (LKK)

00- Not Auth

EXPIRY - \$1500

19/6/20, 11.30am

14 days

L/S

Ry AL Ry

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: