

51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 #01-18 Heavy Vehicle #01-08 Spray Painting #02-27

Singapore 417921 Tel No : 65 6842 0051 Fax No : 65 6741 0510

E-Mail : sales@51.com.sg

Company Reg No : 200616038C

GST Registration No : 200616038C

EASYDRIVE CAR RENTAL

200 JALAN SULTAN #02-38 TENTH CENTRE

SINGAPORE 199018

Contact : 87522272

12/11

X1000 100g

ESTIMATE

Repair Code : C1 M16275

Date in : 18/06/2020

Vehicle Num : SI Q6069G

Model : HONDA VEZEL HYBRID 1.5 AUTO

Chassis Eng# : RU31213086/LEB5913095

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
FRONT RH DOOR <i>seated</i>	1	950.00	✓ 950.00
FRONT RH DOOR BLACK TAPE <i>nee</i>	1	18.50	✓ 18.50
FRONT RH DOOR GLASS CHANNEL WEATHER STRIP <i>cut</i>	1	88.50	✓ 88.50
FRONT RH DOOR GLASS CHANNEL WEATHER STRIP SEAL (FRONT) <i>nee</i>	1	30.00	✓ 30.00
FRONT RH DOOR INNER RUBBER STOPPER L/R <i>nee nee</i>	2	18.50	X 37.00
FRONT RH DOOR INNER TRIM BOARD <i>cracked</i>	1	480.00	✓ 480.00
FRONT RH DOOR LOWER WEATHER STRIP <i>nee nee</i>	1	28.50	X 28.50
FRONT RH DOOR MECHANISM LOCK <i>Damaged</i>	1	196.30	✓ 196.30
FRONT RH DOOR OUTER HANDLE <i>Cracked</i>	1	385.00	21 ✓ 385.00
FRONT RH DOOR OUTER HANDLE INNER RUBBER GASKET <i>nee</i>	1	28.00	✓ 28.00
FRONT RH DOOR OUTER MOULDING <i>2 bond</i>	1	60.00	✓ 60.00
FRONT RH DOOR POWER SWITCH <i>nee nee</i>	1	249.30	X 249.30
FRONT RH DOOR SIDE MIRROR <i>Damaged</i>	1	926.50	✓ 926.50
FRONT RH DOOR SIDE MIRROR COVER <i>repair</i>	1	80.00	X 80.00
FRONT RH DOOR WEATHER STRIP SEAL (REAR) <i>nee nee</i>	1	17.50	X 17.50
FRONT RH DOOR WINDOW GLASS <i>Shattered</i>	1	590.50	✓ 590.50
FRONT RH DOOR WINDOW GLASS REGULATOR <i>Damaged</i>	1	382.90	✓ 382.90

*** This is a computer-generated document which requires no signature.***

page 1

336220

3168.76

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

EASYDRIVE CAR RENTAL

200 JALAN SULTAN #02-38 TEXTILE CENTRE

SINGAPORE 199018

Contact : 87522272

ESTIMATE

Repair Code : CLM16275

Date in : 18/06/2020

Vehicle Num. : SLQ6069G

Model : HONDA VEZEL HYBRID 1.5 AUTO

Chassis/Eng# : RU31213086/LEB5913095

	Subtotal before discount	4,548.50
Percentage discount 20%		909.70
	Sub-total 1	3,638.80
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET <i>NEC</i>	1	50.00 <i>30</i> 50.00
	Subtotal before discount	50.00
Percentage discount 0%		0.00
	Sub-total 2	50.00
	Parts-total	3,688.80

LABOUR

To remove, change window glass.	40	60.00	
To send vehicle for cleaning, shampoo, upholstery and cushion seat.	60	150.00	
To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.	40	100.00	
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	790	300	650.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	350	580.00	
	</		

LKK Auto Consultants hence notify the Repairer of the followings

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

is a computer-generated document which requires no signature.***
page 2

Total: 3989.76

H/S: 3.2K

03 Days.

3.2K