

18/06/2020

MS First Capital Insurance Ltd

Singapore

Attn. : Motor Claim Department

Re : Estimated Quotation

Vehicle No. SJX 2948H Audi A4

S/N	Amount (\$)
A PART REPLACEMENT	
Rear bumper	\$ 1,238.90
Rear bumper reinforcement	\$ 563.90
Rear bumper bracket	\$ 135.30
Rear bumper spoiler	\$ 365.90
Reverse sensor	\$ 218.60
Tail lamp right	\$ 387.00
Rear right fender	\$ 2,154.60
Tail lamp ventilation cover	\$ 104.10
Tail lamp lower garnish	\$ 183.00
Glass sealant	\$ 70.00
Sub-Total	\$ 5,421.30
less 5%	\$ 5,149.90
LABOUR CHARGE	
B	
To repair damaged on rear right accident. Cut, reweld rear right fender and readjustment.	\$ 1,100.00
Remove rear windscreen glass and refix	\$ 150.00
Remove rear quarter glass	\$ 100.00
Remove petrol tank	\$ 200.00
Remove upholstery	\$ 150.00
Respraying rear accident area	\$ 700.00
Apply sealant on welded area	\$ 80.00
GRAND TOTAL OF A & B	\$ 7,629.90

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before other spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Block 176 #03-08 Sin Ming Autocare
Sin Ming Drive
Singapore 575721
Tel : 64532237 / 64530797
Fax : 64556384

Not Authorized
L1 Imp & 7
Returning After Paint
6 days

✓
?
?
✓
✓
?
?
?
4052

700d
120L
60d
60d
100d
600d
30d