

Date: 01.06.2020
 Vehicle No: SJY3925L
 Model: SUZUKI SX4
 Chassis: JSAGYA21S00340611-2010
 Reg. Year: 2010

Third Party Insurer: MS FIRST CAPITAL
 Third Party Veh No: SH9126U
 Date of Accident: 30.05.2020

Not Authorized
11 Smp @ 7
Repair After Paint *4 days*

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>Bu</i> \$790.45 ✓
2	FRONT BUMPER CLIPS	8	\$5.80	<i>Ma</i> \$46.40 ✓
3	FRONT BUMPER SIDE BRACKET RH	1		<i>n</i> \$17.95 x
4	FRONT FENDER RH	1		<i>Bu</i> \$272.20 ✓
5	FRONT FENDER INNER LINER RH	1		<i>Dir/GM</i> \$58.65 ✓
6	FRONT FENDER INNER LINER CLIPS RH	8	\$5.80	<i>Ma</i> \$46.40 ✓
7	FRONT FENDER "VVT" EMBLEM RH	1		<i>Ma</i> \$52.20 ✓
8	FRONT WHEEL ARCH EXTENTION COVER RH	1		<i>Bu</i> \$195.80 ✓
9	FRONT HEADLAMP RH	1		<i>Ca</i> \$369.05 ✓
10	FRONT DOOR RH	1		REPAIR ✓
SUB TOTAL				\$1,849.10
LESS 15%				-\$277.37
PARTS TOTAL				\$1,571.74

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REFIX, REPLACE, REPAIR & READJUST FRONT ACCIDENT AREAS & ETC.

\$600.00 *400*

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT BUMPER, FRNT FENDER RH, FRONT DOOR RH & ETC.

\$700.00 *600*

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00 *20*

LABOUR TOTAL \$1,380.00

TingAn	LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:	TOTAL	\$2,951.74
--------	---	-------	------------

Head office

6 Kung Chong Road Singapore 159143
 Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
 Tel: (+65) 6484 9919 | Fax: (+65) 6481 1011

Branch

551 Upper Thomson Road Singapore 574415
 Tel: (+65) 6452 6868 | Fax: (+65) 6452 9223

