

ASS. REC. BY:

Steve

FILE NO.

CS/SGK20006451/ESF3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Public Liability

To Inspect Vehicle No: _____

at Workshop m/s: _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMS 7885M Yr Regn: 1Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW M3 Coupe 4.0 c.c. 3999Colour: Yellow A/C: Insured / Std / NI / NASp. Reading: 102951 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBSK G 92950 E 698123Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S Rim / STD A/Rim orTyre Size: F: 235/492R19R: 11BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 17/6/20 D.O.I. 19/6/20Survey held at Link@AMK Parking Lot

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front RH

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

SUBMIT P/P \$ 600.00/2 DAYS

\$ 13,010.00/RED - 96%)

Date/Time, File Pass to?

23/06/2020

1) TYPIST

Date/Time, File Return to?

2)

Report Format :

Lump Sum 1.B.B (\$ \$ 600.00 P/P)Days Of Repair: 2Resurvey No. of Trip: 0

Add Fee:

☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

3 + RS. SI

Photos

Others

TOTAL

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: samuel.auburnauto@gmail.com

Vehicle No: SMS7885M

Model: BMW M3

QTY	Description	Repairer's Estimate	
Spare Parts - List Items			
1	Rear Panel Bumper Front RH Rim / CUT	\$	3,200.00
1	Rear Panel Bumper Side Retainers X	\$	350.00
1	Panel Bumper Reflectors X	\$	720.00
1	Rubber Moulding X	\$	120.00

\$ 4,390.00

c/f: \$	\$	4,390.00
---------	----	----------

	Special Nett Items	AMT S\$
1	Rear Carbon Fibre Panel	\$ 6,800.00
1	Rear L/H Panel bumper clip	\$ 150.00
		\$ 6,950.00

S/N. Labour Charges

1	Remove and refit rear Carbon Fibre Panel	\$ 500.00
2	Remove and refit rear Panel bumper	\$ 500.00
3	Remove, refit and replaced damage and check up rear electrical wiring	\$ 150.00
4	Remove and refit inner garnishes trim to assist repair	\$ 200.00
5	To apply undercoating on replaced panel	\$ 120.00
6	To Respray Painting.	\$ 800.00
		\$ 2,270.00
	GRAND TOTAL	
		\$ 13,610.00

Survey:

1st / 2nd / 3rd

(delete accordingly)

Surveyor Details:

(Name) Steve (LKK)
(Contact) 8522 8813
(Email) _____
(Signature) 
(Date/Time) 19/6/20, 2.30 pm
with Neil

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: