

AUBURN AUTO PTE LTD

176 Sin Ming Drive #04-18 Sin Ming Autocare, Singapore 575721

Tel : +65 9787 5558

Email: samuel.auburnauto@gmail.com

Vehicle No: SMS7885M

Model: BMW M3

QTY	Description	Repairer's Estimate
Spare Parts - List Items		
1	Rear Panel Bumper Front RH Rim / CUT	\$ 3,200.00 500 / (net price)
1	Rear Panel Bumper Side Retainers X N/A	\$ 350.00 X
1	Panel Bumper Reflectors X N/A	\$ 720.00 X
1	Rubber Moulding X N/A	\$ 120.00 X

\$ 4,390.00

c/f: \$ 4,390.00

Special Nett Items		AMT \$	
1	Rear Carbon Fibre Panel	\$	6,800.00 X
1	Rear L/H Panel bumper clip	\$	150.00 X
		\$	6,950.00

S/N. Labour Charges

1	Remove and refit rear Carbon Fibre Panel	\$	500.00 X
2	Remove and refit rear Panel bumper	\$	500.00
3	Remove, refit and replaced damage and check up rear electrical wiring	\$	150.00 X
4	Remove and refit inner garnishes trim to assist repair (Remove, Refit From RH Rim Alignment)	\$	200.00 100 /
5	To apply undercoating on replaced panel	\$	120.00 X
6	To Respray Painting.	\$	800.00 X
		\$	2,270.00

GRAND TOTAL

\$ 13,610.00


P-500
L-100
P/P-600

Survey:

1st / 2nd / 3rd

(delete accordingly)

Surveyor Details:

(Name) Steve (LKK)
(Contact) 8322 8813
(Email) _____
(Signature) 
(Date/Time) 19/6/20, 2.30 pm
WHL Pril

2 dgs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: