



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

TOKIO MARINE INSURANCE SINGAPORE LTD Ref : CS/SGK20006451/Esf3e2

c/o SEDGWICK SINGAPORE PTE LTD
30 CECIL STREET, LEVEL 12
PRUDENTIAL TOWER
SINGAPORE 049712 SINGAPORE 069046

Date : 26-06-2020



Code : TMI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SMS 7885M
Policy No.	G2002877	Coverage (\$)	0.00
Claim No.	IA2020-50742/6000751/TWC	Excess (\$)	0.00
Assign From	TAN WEE CHIAU	Assign Date	19/06/2020

2. Vehicle Particulars & Condition

Make & Model	BMW M3 COUPE 4.0	c.c	3999
Engine No.	HIDDEN	Year of Reg.	
Chassis No.	WBSKG92050E698123	Colour	YELLOW
Odometer	102951	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/40Z R19	MICHELIN	5 mm
L/H Front Tyre	235/40Z R19	MICHELIN	5 mm
R/H Rear Tyre	235/40Z R19	MICHELIN	5 mm
L/H Rear Tyre	235/40Z R19	MICHELIN	5 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/06/2020	Inspection Date	19/06/2020
Survey held at	3 ANG MO KIO STREET 62 LINK @AMK, #01-45		
Repairer	AUBURN AUTO PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------