

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 8402R

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BONNET (SN)	SERVICEABLE	1,067.55	-
1	BONNET, HINGE - RH (SN)	SERVICEABLE	101.84	-
1	HEADLAMP RHS (SN)	BROKEN	1,021.15	1,021.15
1	RADIATOR GRILLE (SN)	SERVICEABLE	812.00	-
1	FRONT BUMPER, TOP (SN)	DEFORMED	898.08	898.08
1	FRONT BUMPER, LOWER (SN)	SERVICEABLE	766.08	-
1	BUMPER BRACKET RHS (SN)	NECESSARY	35.30	35.30
1	BUMPER BRACKET LHS (SN)	SERVICEABLE	35.30	-
1	ORNAMENT, BUMPER RHS (SN)	SERVICEABLE	78.73	-
1	FRONT FENDER RHS (SN)	BUCKLED	298.80	298.80
1	FR MUDGUARD PROTECTION - RH (SN)	TORN	274.61	274.61
1	END PLATE RHS (HEADLAMP) (SN)	SERVICEABLE	262.56	-
1	MOULDING, FT PILLAR - RH (SN)	SERVICEABLE	120.08	-
1	BOXED PANEL (SN)	SERVICEABLE	318.23	-
1	SUNDRIES (SN)	NECESSARY	80.00	30.00
			6,170.31	2,557.94
	<u>LABOUR</u>			
	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK.		180.00	120.00
	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.		2,600.00	1,200.00
	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC.		1,600.00	700.00
				-
			4,380.00	2,020.00
	GRAND TOTAL		10,550.31	4,577.94
	RECOMMENDED COST OF LUMP SUM REPAIRS			3,650.00
	(TO ITS PRE-ACCIDENT CONDITION)			3,000.00
	LESS EXCESS			-500.00

NETT LIABILITY 3,150.00

Report Ref No. CS/LPC20006461/R1qf3e2





Report Ref No. CS/LPC20006461/R1qf3e2

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.