

SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 6451 7420

ESTIMATE

AM CHEF CATERING PTE LTD

c/o 46 Lenton plain
Singapore 786547

Date: 19/6/2020

QUANTITY	PARTICULARS	AMOUNT (\$)
	<u>RE: TOYOTA HIACE / GBK 1568 R</u>	
1 pc	Rear Tail Lamp	385.90
1 pc	Rear Tail Lamp Lower Panel	126.30
1 pc	Rear Bumper	466.90
	sub total	979.10
	Less 25%	244.78
	sub total	734.33
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.	400.00
	To check wiring system.	50.00
	To apply putty & spray painting on affected areas.	600.00
	To install reverse sensors & reverse camera.	80.00
	total	1,864.33

Remark:
Tyre: Bridgestone 195 x 15c