

# SUPREME AUTO SERVICE PTE LTD

176 SIN MING DRIVE #02-01 SINGAPORE 575721  
TEL: 6452 8211 FAX: 6451 7420

## ESTIMATE

AM CHEF CATERING PTE LTD  
c/o 46 Lenton plain  
Singapore 786547

*Not Authorized*

*Repairing B4 paint*

*6/12/20 8850/4*

*3 days*

Date: 19/6/2020

| QUANTITY | PARTICULARS                                                                                              | AMOUNT (\$)             |
|----------|----------------------------------------------------------------------------------------------------------|-------------------------|
|          | <b>RE: TOYOTA HIACE / GBK 1568 R</b>                                                                     |                         |
| 1 pc     | Rear Tail Lamp                                                                                           | <i>Pen</i> 385.90 X     |
| 1 pc     | Rear Tail Lamp Lower Panel                                                                               | <i>n</i> 126.30 X       |
| 1 pc     | Rear Bumper                                                                                              | <i>Pen/Ref</i> 466.90 ✓ |
|          | sub total                                                                                                | 979.10                  |
|          | Less 25%                                                                                                 | 244.78                  |
|          | sub total                                                                                                | 734.33                  |
|          | To remove and replace the parts mentioned above,<br>panel beat and realign the necessary affected areas. | <i>250/</i> 400.00      |
|          | To check wiring system.                                                                                  | <i>na</i> 50.00 X       |
|          | To apply putty & spray painting on affected areas.                                                       | <i>400/</i> 600.00      |
|          | To install reverse sensors & reverse camera.                                                             | <i>50/</i> 80.00        |
|          | total                                                                                                    | 1,864.33                |

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Remark:  
re: Bridgestone 195 x 15c